

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22005917/KNY3E2

Date: 15/07/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No: MCF22A00000100
Claimant Vehicle No : SHB7642X Insured Vehicle No : SMD962Z
Date of Loss: 21/06/2022 Nature of Claim: TP Claim No: DMCF2200103H/02/03/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7642X
Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR2C34064
Reg. Date: 27/06/2019 (Man. Year: 2018) Chassis No: JTDKB3FU303081976
Colour: Metallic Pearl White/Red Odometer: 283828 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: LANVIGATOR 7 mm Rear Left Side: Sailun 8 mm
Front Right Side: LANVIGATOR 7 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,850.32	2,207.27	4,643.05	67.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,920.00	755.00	8,165.00	91.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,770.32	2,962.27	12,808.05	81.22
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	15,770.32	2,350.00	13,420.32	85.10
+ GST 7.00/7.00% (S\$)	1,103.92	164.50	939.42	85.10
Nett Amount (S\$)	16,874.24	2,514.50	14,359.74	85.10

INSPECTION

Date of Assignment: 21/06/2022
Date Inspected: 22/06/2022 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7642X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER,REAR BUMPER,LOWER	Dented	15.40 FL	*15.40 FL
4	1		*GUARD,REAR BUMPER,CENTER	Dented/Cracked	576.30 FL	*576.30 FL
5	1		*RETAINER,REAR BUMPER,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER,REAR BUMPER,RH	Serviceable	117.70 FL	*- FL
7	1		*FILLER,REAR BUMPER EXTENSION,RH	Serviceable	123.70 FL	*- FL
8	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Mtg Cracked	925.60 FL	*925.60 FL
9	1		*WEATHERSTRIP,BACK DOOR	Serviceable	372.30 FL	*- FL
10	1		*COVER,FLOOR UNDER,NO 1 LH	Serviceable	175.10 FL	*- FL
11	1		*COVER,FLOOR UNDER,NO 2 RH	Serviceable	241.90 FL	*- FL
12	1		*COVER,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
13	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
14	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	*- FL
15	1		*SEAL,REAR BUMPER SIDE RH	Serviceable	88.50 FL	*- FL
16	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	*- FL
17	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	*- FL
18	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	*- FL
19	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	*- FL
20	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.90 FL	*47.90 FL
21	1		*REAR TAILGATE WORDING PRIUS	Necessary	54.60 FL	*54.60 FL
22	1		*REAR TAILGATE WORDING HYBRID	Necessary	54.60 FL	*54.60 FL
23	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
25	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
27	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
28	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
29	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
30	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
31	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
32	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
33	1		*SET TAILLAMP LOWER CLIP	Not Necessary	55.00 FS	*- FS
34	1		*SET TAILLAMP UPPER CLIP	Not Necessary	55.00 FS	*- FS
35	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
36	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,462.10	2,819.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,611.78	612.43
Total Parts (\$\$)	6,850.32	2,207.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	250.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			8,920.00	755.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >