

Not Notarised  
L1 Reg & 2350/1

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7642X

AAD2206-085.

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JUN 2022

SHB7642X

JTDKB3FU303081976

200303878K

TOYOTA

PRIUS

21/06/2022

SMD962Z/ECICS

27/06/2019

PART		LIST	
1	COVER, REAR BUMPER	\$ Bu	442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ B	332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$ m	15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$ Pull out	576.30 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$ SL	116.50 X
1	RETAINER, REAR BUMPER SIDE, RH	\$ SL	117.70 X
1	FILLER, REAR BUMPER EXTENSION, RH	\$ SL	123.70 X
1	PANEL SUB-ASSY, BACK DOOR	\$ R	1,147.80 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ m to m	925.60 ✓
1	WEATHERSTRIP, BACK DOOR	\$ SL	372.30 }
1	COVER, FLOOR UNDER, NO.1 LH	\$ SL	175.10 }
1	COVER, FLOOR UNDER, NO.2 RH	\$ SL	241.90 }
1	COVER, REAR FLOOR CTR	\$ SL	229.90 }
1	COVER, DECK TRIM, REAR	\$ SL	126.70 } X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ R	650.30 }
1	SEAL, REAR BUMPER SIDE, RH	\$ SL	88.50 }
1	STAY ASSY, BACK DOOR, LH	\$ SL	242.50 }
1	STAY ASSY, BACK DOOR, RH	\$ SL	242.50 }
1	HINGE ASSY, BACK DOOR, LH	\$ R	61.00 }
1	HINGE ASSY, BACK DOOR, RH	\$ R	61.00 }
1	REAR TAILGATE TOYOTA LOGO	\$ m	47.90 ✓
1	REAR TAILGATE WORDING 'PRIUS'	\$ m	54.60 ✓
1	REAR TAILGATE WORDING 'HYBRID'	\$ m	54.60 ✓
TOTAL		\$	6,447.10
25%		\$	1,611.78
		\$	4,835.33

**Trans-cab Auto Services Pte Ltd****AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7642X****Special Nett**

1SET PARKING AID	\$	<i>nd</i> 700.00	<i>220SN</i>
1SET REAR BUMPER CLIP	\$	<i>nn</i> 95.00	<i>60SN</i>
2 WINDSCREEN SEALANT	\$	<i>nn</i> 150.00	<i>X</i>
1 WINDSCREEN MOULDING	\$	<i>nn</i> 200.00	<i>X</i>
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 130.00	<i>X</i>
1 REAR TAILGATE STICKER "Trans-Cab"	\$	<i>nn</i> 80.00	<i>30SN</i>
1 REAR TAILGATE STICKER "6555-3333"	\$	<i>nn</i> 80.00	<i>30SN</i>
1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 180.00	<i>30SN</i>
1SET REAR BUMPER RETAINER CLIP	\$	<i>nn</i> 85.00	<i>X</i>
1 REAR NUMBER PLATE WITH HOLDER	\$	<i>nn</i> 140.00	<i>X</i>
1SET TAILLAMP LOWER CLIP	\$	<i>nn</i> 55.00	<i>X</i>
1SET TAILLAMP UPPER CLIP	\$	<i>nn</i> 55.00	<i>X</i>
1 END PANEL TRIM CLIP	\$	<i>nn</i> 65.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>2,015.00</b>	

**TOTAL PARTS \$ 6,850.33****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 *X*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *2501*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 *X*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 *X*

**Trans-cab Auto Services Pte Ltd****AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7642X**

To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	h	380.00	X
To check steering geometry and computer wheel alignment	\$	h	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	h	250.00	X
Towing Fees	\$	h	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	4401
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	h	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>8,920.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>15,770.33</b>	

**(PART-BY-PART) Repair Days**

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**25 DAYS**  
2 1/2 days