

ASS. REC. BY:

REF:

CS/ SM R 22005919/ T 43.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 4156

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKL 7605R Yr Regn: 2018, outType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi Q5 c.c. 1984Colour: white A/C: ☒ Insured / Std / NI / NASp. Reading: 41394 T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: WIAU 222F7732126597Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt or _____Brake: ☒ Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / ☒ S/Rim / STD A/Rim or _____Tyre Size: F: 235/55R19R: 235/55R19☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 24/6/22Survey held at Premium AbtDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / L.B. (\$ _____)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0509/2022/TP
DATE : 21-Jun-22
WIP : 29503

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/6/22

YOUR INSURED VEH NO : SHB 5503 C

STRIKES AUTOMOTIVE SERVICES Pte Ltd

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Attn : Motor Claims Dept

Tel: 6866 2615 - Fax: 6368 7421

OWNER'S NAME : MR TAN JIE ERN, JONATHAN
ADDRESS : 62 JALAN LEMBAH THOMSON
SINGAPORE 577532
TELEPHONE : HP +65 98255665
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800119421-02
VEHICLE NO : SKL 7605 R
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 11/10/2018
ENGINE NO : DAX 031352
CHASSIS NO : WAUZZZF7J2126597
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jun-22
PLACE OF ACCIDENT : THOMSON RIDGE SLIP ROAD TO
UPPER THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 7605 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	800
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	3,000.00	2200
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 7605 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 2,030.00	RP
2	REAR BUMPER - LOWER	1	\$ 1,330.00	de ✓
3	REAR BUMPER SPOILER	1	\$ 967.00	de ✓
4	REAR BUMPER TOWING EYE - RH	1	\$ 33.00	X
5	REAR BUMPER CLOSING ELEMENT - RH	1	\$ 108.00	?
6	REAR BUMPER CHROME TRIM - RH	1	\$ 265.00	?
7	REAR BUMPER TAIL LIGHT - RH	1	\$ 779.00	can ✓
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,043.00	?
9	REAR BUMPER SEAL - LH / RH	2	\$ 7.00	?
10	REAR BUMPER HOLDING STRAP	1	\$ 189.00	rec ✓
11	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,230.00	plus to ?
12	REAR PARKING AID SENSOR	2	\$ 530.00	X
13	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	rec ✓
14	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 8,821.00	
TOTAL LABOUR CHARGES		:	\$ 4,752.00	
GRAND TOTAL		:	\$ 13,573.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanfikh 97495749/62563561
WP 24/6/22 @ 1050
tanfikh@lkhauto.com
3 days
Resurvey before paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT