

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0509/2022/TP
DATE : 21-Jun-22
WIP : 29503

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/6/22

YOUR INSURED VEH NO : SHB 5503 C

STRIKES AUTOMOTIVE SERVICES Pte Ltd

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Attn : Motor Claims Dept

Tel: 6866 2615 - Fax: 6368 7421

Hi Taufikh

3 days - ok - Johnny Boo

30-Aug-22

OWNER'S NAME : MR TAN JIE ERN, JONATHAN
ADDRESS : 62 JALAN LEMBAH THOMSON
SINGAPORE 577532
TELEPHONE : HP +65 98255665
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800119421-02
VEHICLE NO : **SKL 7605 R**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 11/10/2018
ENGINE NO : DAX 031352
CHASSIS NO : WAUZZZF7J2126597
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jun-22
PLACE OF ACCIDENT : THOMSON RIDGE SLIP ROAD TO
UPPER THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 7605 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$ 800.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	3,000.00	\$ 2,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,752.00	\$ 3,552.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 7605 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER - UPPER	1	\$ 2,030.00	\$	1,330.00
2	REAR BUMPER - LOWER	1	\$ 1,330.00	\$	965.50
3	REAR BUMPER SPOILER	1	\$ 967.00		
4	REAR BUMPER TOWING EYE - RH	1	\$ 33.00		
5	REAR BUMPER CLOSING ELEMENT - RH	1	\$ 108.00		
6	REAR BUMPER CHROME TRIM - RH	1	\$ 265.00		
7	REAR BUMPER TAIL LIGHT - RH	1	\$ 779.00	\$	778.50
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,043.00		
9	REAR BUMPER SEAL - LH / RH	2	\$ 7.00		
10	REAR BUMPER HOLDING STRAP	1	\$ 189.00	\$	189.00
11	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,230.00	\$	1,230.00
12	REAR PARKING AID SENSOR	2	\$ 530.00		
13	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00		
14	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS			:	\$ 8,821.00	\$ 4,493.00
TOTAL LABOUR CHARGES			:	\$ 4,752.00	\$ 3,552.00
GRAND TOTAL			:	\$ 13,573.00	\$ 8,045.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-21/08/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT