

Vehicle no : YQ1159J

Model : FEB21E

Chassis no : FEB21EA30181

D.O.A : 18/06/2022

TPAXA

VERON

List item :

01ps Front bumper	Distorted		✓	\$	1200	1100
01ps Front bumper bracket	Bent		✓	\$	215	
01ps Front bumper reinforcement	HEW		X	\$	475	
02Ps Front bumper side garnish	LH Missing	2H int	✓	\$	360x2 = 720	620
01ps Front bumper inner bracket	HEW		X	\$	95	
01ps Front grill	Missing		✓	\$	1120	718
01ps Front grill logo			✓	\$	110	75
01ps Front panel	HEW		X	\$	885	
01ps Front panel emblem (FUSO)	HEW		X	\$	105	
02ps Front headlamp	Cracked	@	✓	\$	530x2 = 1060	
02ps Front side lamp	Cracked	@	✓	\$	285x2 = 570	
02ps Front side reflector		@	✓	\$	250x2 = 500	
02ps Front headlamp panel	HEW	@	X	\$	75x2 = 150	
01ps Front windscreen moulding	HEW		X	\$	285	
02ps Front door hinges	HEW	@	X	\$	75x2 = 150	
01ps Front door (LH)	Buckled		✓	\$	2230	1820
01ps Front door pillar	Bent		✓	\$	1500	980
01ps Front door step panel	Cracked		✓	\$	370	
01ps Front door step garnish	Cracked		✓	\$	690	410
01ps Front door trim board	Deformed		✓	\$	610	
02ps Front door window regulator	HEW		X	\$	395	
01ps Front side mirror (LH)	HEW		X	\$	180	
02ps Front a/c pipe (rubber pipe)	3x4	@	X	\$	280x2 = 560	
01ps Front a/c suction hose	HEW		X	\$	175	
01ps Front a/c discharge hose	Dented		✓	\$	525	315

14,875.00

01ps Front cabin *Reps*
 01ps Front console box *3 new*
 02ps front cabin bracket
 01ps Diesel tank *Dented*
 01set Diesel tank bracket *Distorted*
 01ps Diesel tank meter float *New*
 01ps Adblue tank *3 new*
 01ps Adblue tank bracket *new*
 01ps Lower side reinforcement (RH) *Distorted*
 01ps Rear rim (RH) *New*
 01ps Rear taillamp (RH) *LH New*
 01ps Rear taillamp bracket *Best*
 01ps Rear step panel *Dented*
 01ps Rear reinforcement *Best*
 01ps Rear tailgate rubber stopper (RH) *3 new*
 01ps Rear side tailgate rubber (RH) *new*

X \$ -
 X \$ 130
 X \$ $15 \times 2 = 30$
 ✓ \$ ~~2010~~ 1980
 ✓ \$ 195
 X \$ -
 X \$ 770
 X \$ 85
 ✓ \$ 550
 X \$ 150
 ✓ \$ 230
 ✓ \$ ~~275~~ 195
 ✓ \$ 195
 ✓ \$ 780
 X \$ 15
 X \$ 15

5430

Total :

Less 25%:

TOTAL :

Special Nett :

01ps Front door sticker (co logo) *new*
 01ps Front door sticker (BLUETEC) *new*
 01ps windscreen sealant *New*
 01ps Front number plate *Best*

\$ 65.00 ✓

\$ 35.00 ✓

\$ 80.00 X

\$ 35.00 ✓

Total : \$ 215.00

13078

less 25% 9808.50

135

Labour :

- 01) To supply labour to repair and replace above mentioned parts
- 02) To supply labour and paint to spray accident affected area
- 03) To supply labour to remove and refit front windscreen
- 04) To supply labour to remove and refit dashboard for repair word
- 05) To supply labour to spray anti rust on panel
- 06) To supply labour to re-wire replace parts
- 07) To supply labour to refill a/c gas
- 08) To supply labour to conduct wheel alignment
- 09) To supply labour to straighten front chassis frame

: \$ 3500 ~~1500~~
 : \$ 3000 ~~1300~~
 : \$ 350 +
 : \$ 450 +
 : \$ 250 ~~150~~
 : \$ 180 ~~60~~
 : \$ 120 ~~80~~
 : \$ 150 +
 : \$ 450 +

TOTAL : \$ 8450

23,893.75

Adrian Li

H/S 12 Days.

Total: 13133.50

H/S: 10.5K

10.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: