

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD521Y

NOT AUTHORIZED
L1 Samp @ 3950/yr

AAD2206-

Vehicle No.:
Chassis No.:
UEN No:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

22 JUN 2022

SHD521Y
VF1ABL15AUC283404
200303878K
RENAULT
LATITUDE
20/06/2022
YM8002C/LONPAC
17/11/2017

PART	LIST	Price	Status
1 BUMPER COVER REAR	Be	561.70	✓
1 BUMPER LOWER REAR	Be	411.90	✓
1 BUMPER BRACKET CTR REAR	Sm	98.10	X
1 BUMPER BRACKET SIDE RH REAR	Sm	82.10	X
1 BUMPER RETAINER RH REAR	Sm	59.80	X
1 BUMPER BRACKET SIDE LH REAR	Sm	80.80	X
1 BUMPER RETAINER LH REAR	Sm	54.20	X
1 ABSORBER REAR	NIP	217.30	X
1 BUMPER BEAM REAR	Be	547.80	✓
1 BUMPER BEAM BRACKET LH REAR	R	114.50	X
1 BUMPER BEAM BRACKET RH REAR	R	114.50	X
1 OUTER PANEL REAR (End Panel)	R	745.80	X
1 OUTER PANEL REAR (End Panel)TRIM	Sm	404.56	X
1 TAILLAMP LH	mbcm	401.40	✓
1 TAILLAMP RH	Sm	401.40	X
1 BOOT REAR	Be	1,677.20	✓
1 BOOT BADGE 'RENAULT'	ma	82.40	✓
1 BOOT BADGE	ma	95.80	✓
1 BOOT REFLECTOR LAMP LH	CMT	277.70	✓
1 BOOT HINGE LH	R	254.20	X
1 BOOT HINGE RH	R	254.20	X
1 BOOT STRUT LH	Sm	145.10	X
1 BOOT STRUT RH	Sm	145.10	X
1 BOOT LOCK	R	246.60	X
1 BOOT LOCK CATCH	R	41.70	X
1 BOOT FINISHER	Sm	344.70	X
		7,860.56	
	10%	786.06	
		7,074.50	

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-

SHD521Y

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	305N-
1 REAR BOOT STICKER '6555-3333'	\$	80.00	305N-
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
1 REAR BUMPER ADVERTISEMENT STICKER	\$	100.00	605N
TOTAL	\$	1,632.00	
TOTAL PARTS	\$	8,706.50	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	440d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	400d
To Rust-Proofing Of The Affected Areas.	\$	170.00	30d
To reinstall rear bumper parking sensor.	\$	170.00	60d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60d
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD521Y

To Check Electrical Lighting Concerned.

\$

170.00 *200*

TOTAL \$

5,580.00

Over All Total \$

21,361.01

(LUMP SUM)

Repair Days

14 DAYS
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/06/2022 17:26 (SGT)
Date of Accident 20/06/2022 14:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG WOODLANDS AVE 12 JUNCTION OF WOODLANDS
AVE 1 TOWARDS GAMBAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD521Y

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXXX78K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No (Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer Renault
Model LATITUDE 2.0L DCI AUTO D/AB 4DR
Variant -
Exact purpose for which vehicle was being used at time of
accident Private hire
Are you claiming under your own insurance policy for repair to
your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1998


INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number -

DRIVER

Name of Driver CHUA POH HIN

ACCIDENT DIAGRAM



**VERIFIED BY AJAX MARS (ARC)
 REPORTING OFFICER
 ANG QI HAO, VICTOR**

 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20220621/2020

2 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20220621/2020

CONTINUATION OF REPORT

Driver			
Name	CHUA POH HIN	ID No.	S1512959Z
Related Vehicle	SHD521Y (Car)	Contact No.	83386370
Hospital/Clinic	ONECARE CLINIC BOON LAY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/06/2022	Date Discharge	20/06/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	GUNASEKARAN GNANAMANI	ID No.	G6566195P
Related Vehicle	YM8002C (Lorry)	Contact No.	93711691
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/06/2022 at about 1445hrs, I was driving along Woodlands avenue 12 towards Woodlands Avenue 10. While at the junction of Woodlands Avenue 1, the traffic light was red. Thus, I stopped my vehicle at the stop line of Lane 2. Suddenly, i felt an impact from the rear. Thereafter, i alighted to make a check and discovered that a lorry had collided into the rear of my vehicle. The boot of my vehicle suffered a dent . As a result, the boot was unable to be closed and the sensor was damaged. I also suffered pain at my neck. I went to see a doctor and was given 3 days medical leave. No police or ambulance attended to the accident. No government property was damaged.