

ASS. REC. BY:

REF:

6PL/22005931/Kc

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____ Consistent? : Yes or No

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S1HD 5214 Yr Regn: 11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AJ

Make: Renault Latitude c.c 1995

Colour M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 377384 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15AUC 283404

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pairum

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 8 mm

L/Bal. 6 mm L/Bal. 8 mm

D.O.A. 20/6/22 D.O.I. 22/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Crat BL</u>
<u>23/6/22</u>	<u>1 Rep @ 3950. Car had</u>

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____ Date/Time, File Return to? 2) _____

Days Of Repair: _____ Resurvey No. of Trip: _____

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee: _____

Transportation: _____

S - RS: \$ _____

Fines: _____

Others: _____

TOTAL: _____

Report Format : _____ Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD521Y

Not Authorized
L1 Pmg @ 3950/n

AAD2206-

Vehicle No.:
 Chassis No.:
 UEN No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

22 JUN 2022

SHD521Y
 VF1ABL15AUC283404
 200303878K
 RENAULT
 LATITUDE
 20/06/2022
YM8002C/LONPAC
 17/11/2017

PART	LIST	
1 BUMPER COVER REAR	\$	<i>Beu</i> 561.70 ✓
1 BUMPER LOWER REAR	\$	<i>nd</i> 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$	<i>su</i> 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>su</i> 82.10 X
1 BUMPER RETAINER RH REAR	\$	<i>su</i> 59.80 X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>su</i> 80.80 X
1 BUMPER RETAINER LH REAR	\$	<i>su</i> 54.20 X
1 ABSORBER REAR	\$	<i>NIP</i> 217.30 X
1 BUMPER BEAM REAR	\$	<i>Beu</i> 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 114.50 X
1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 745.80 X
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>su</i> 404.56 X
1 TAILLAMP LH	\$	<i>m3cm</i> 401.40 ✓
1 TAILLAMP RH	\$	<i>su</i> 401.40 X
1 BOOT REAR	\$	<i>Beu</i> 1,677.20 ✓
1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 82.40 ✓
1 BOOT BADGE	\$	<i>na</i> 95.80 ✓
1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 277.70 ✓
1 BOOT HINGE LH	\$	<i>n</i> 254.20 X
1 BOOT HINGE RH	\$	<i>n</i> 254.20 X
1 BOOT STRUT LH	\$	<i>su</i> 145.10 X
1 BOOT STRUT RH	\$	<i>su</i> 145.10 X
1 BOOT LOCK	\$	<i>n</i> 246.60 X
1 BOOT LOCK CATCH	\$	<i>n</i> 41.70 X
1 BOOT FINISHER	\$	<i>su</i> 344.70 X
	\$	7,860.56
10%	\$	786.06
	\$	7,074.50

Specical Nett

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHD521Y

1SET PARKING AID	\$	na	700.00	X
1SET REAR BUMPER CLIP	\$	na	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	30sal
1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	30sal
2 WINDSCREEN SEALANT	\$	na	150.00	X
1 WINDSCREEN MOULDING	\$	na	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
1 REAR BUMPER ADVERTISEMENT STICKER	\$	na	100.00	60sal

TOTAL	\$	1,632.00
TOTAL PARTS	\$	8,706.50

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	440l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	400l
To Rust-Proofing Of The Affected Areas.	\$	170.00	30l
To reinstall rear bumper parking sensor.	\$	170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60l
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na	170.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD521Y

To Check Electrical Lighting Concerned. \$ 170.00 *2cl.*

TOTAL \$ 5,580.00

Over All Total \$ 21,361.01

(LUMP SUM)

Repair Days

~~14 DAYS~~

3 days

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: