

08/11/13 wef
ASS. REC. BY: Phan

REF:

CS/AIS 22005932/Ruy3

960C

COE EXPIRY: 2032/MAY

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMU 36886

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA LN

Insured: AIS

Policy No. SP2001915279

Claims No. 202222005274SL

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

141K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 36886

Yr Regn: 2012 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 640I 3.0 AT

c.c. 2979

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

226486

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBALW720900K15108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/35R19

R:

19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/06/22

D.O.I.

22/06/22

Survey held at

PERFORMANCE

Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 47K

4/7/22

Submit uneconomical T/L-mv:\$141k Ita:\$93,065 nv:\$47,935
revised fig \$64,605.86 check items \$102,682.40

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 4/7/22-typist

Days Of Repair: 22

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62226
Date Estimated : 21/06/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 9

- ESTIMATE REPAIR FOR -

Lim Kuan Yiou
36 Pavilion Grove

Singapore
Singapore 658628

- ACCOUNT - 137

Allianz Global Corporate & Specialty SE
Singapore Branch
12 Marina View
Singapore 018961
#14-01 Asia Square Tower 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	640iA-C	135877

DESCRIPTION

VALUE

To replace bumper front panel, both front side panels, bonnet, front panel	20,400.00
2 attachments, both front engine supports, both front wheelhouses, and repair accident related area.	5100
To spray paint bumper front panel, both front side panels, bonnet, both engine supports, both front wheelhouses, both front doors and both front A pillars.	4106 8,341.00
To replace right headlight.	456 481.00
To replace left headlight.	456 481.00
To replace front windscreen glass.	574.00
To remove and install IU unit bracket.	31.00
To conduct water leak tests.	75.00
To supply and install front windscreen solar film.	531.00
To supply front emboss number plate.	83.00
To send vehicle with new short engine to LTA for inspection.	? 191.00
Being charge for LTA inspection fees.	? 80.00
To replace new short engine and adjust engine timing accordance to BMW specification.	? 8,496.00
Fully Synthetic Engine Oil	? 429.00
To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).	784 826.00

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 62226**
Date Estimated : **21/06/2022**
Prepared By : **Foong Shiuh Jye**

Page No. : 2 of 9

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	6401A-C	135877

DESCRIPTION

VALUE

To replace auxiliary radiator assembly including pressure test, bleed cooling system and conduct check for leak.	728 767.00
To replace engine oil cooler, both oil cooling inlet and outlet pipes including top up engine oil and conduct check for leak.	616 649.00
To replace engine oil heat exchanger including top up engine oil and conduct check for leak.	504 531.00
To replace charge air cooler including conduct check for leak and proper function.	504 531.00
To replace front exhaust silencer including alignment system and conduct check for leak.	504 ? 531.00
To replace exhaust manifold and gasket including conduct check for leak.	1064 ? 1,121.00
To remove and install front suspension to facilitate the jacking of chassis and mounting of car on celette bench including replace damaged parts.	2522 ? 2,655.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	504 531.00
To replace electromechanical power steering including program, initialize steering column adjustment and conduct check for proper function.	840 888.00
To remove and install rear suspension, rear axle and control system to facilitate the work on celette bench including replace damaged parts.	2522 2,655.00
To replace tyre and wheel rim including balancing. (1x).	376 94.00
To mount accident vehicle on celette bench or Car-O-liner to facilitate re-alignment of body / chassis accordance with BMW specification.	2802 2,950.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	504 531.00
To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series).	952 1,003.00



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 62226**
Date Estimated : **21/06/2022**
Prepared By : **Foong Shiuh Jye**

Page No. : **3 of 9**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	640iA-C	135877

DESCRIPTION	VALUE
To replace front PDC sensor wire harness including reset and conduct check for proper function.	252 268.00
To replace both front seat belts and tensioners including reset and conduct check for proper function.	504 531.00
To replace roof top headlining and both ITS head air bags including reset and conduct check for proper function.	967 1,018.00
To replace front dashboard passenger air bag including reset and conduct check for proper function.	504 531.00
To carry out body cavity preservation. (Per panel).	112 118.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	280 295.00
Sundries.	150.00
Total Labour 1:	59,362.00

DESCRIPTION	QTY	PRIC	VALUE
(S/L) EXCHANGE SHORT ENGINE ?	1	32,534.30	32,534.30
COOLANT HOSE ?	1	89.25	89.25
POWER STEERING COOLER ?	1	236.50	236.50
CHARGE AIR COOLER ?	1	750.60	750.60
COVER MODULE CARRIER ?	1	58.10	58.10
AUXILIARY RADIATOR ?	1	702.95	702.95
MODULE CARRIER ?	1	208.90	208.90
RADIATOR ?	1	1,171.55	1,171.55
COOLANT HOSE ?	1	92.35	92.35
COOLANT HOSE ?	1	138.55	138.55
COOLANT HOSE ?	1	159.05	159.05
HEAT EXCHANGER ?	1	518.20	518.20
FAN SHROUD ?	1	332.35	332.35
FAN HOUSING WITH FAN ?	1	1,368.10	1,368.10
COVER INTERCOOLER ?	1	73.50	73.50
FRONT AXLE SUPPORT ?	1	1,978.45	1,978.45
WISHBONE TOP ?	2	578.10	1,156.20
RH TENSION STRUT W/RUBBER MOUNTING ?	1	525.55	525.55
LH WISHBONE W/RUBBER MOUNTING ?	1	630.65	630.65
RH WISHBONE W/RUBBER MOUNTING ?	1	630.65	630.65
WHEEL HUB WITH BEARING FRT ?	2	494.30	988.60
FRT LH CARRIER ?	1	446.55	446.55

Performance Motors Limited

Darby Motors Company
Reg. No. 197401559W GST Reg. No M2-0020081-x
11-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62226
Date Estimated : 21/06/2022
Prepared By : Foong Shiuh Jye

Page No. : 4 of 9

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	640iA-C	135877

DESCRIPTION	QTY	PRIC	VALUE
FRT RH CARRIER ?	1	453.70	453.70
FRONT SWING SUPPORT ?	2	117.90	235.80
LH TIE ROD ?	1	393.35	393.35
RH TIE ROD ?	1	393.35	393.35
EXCH STEERING BOX ELECTR. ?	1	6,293.65	6,293.65
AIRBAG MODULE DRIVER'S SIDE (SCHWAR ACU)	1	1,765.55	1,765.55
RR DRIVE FLANGE HUB ?	2	221.75	443.50
OUTPUT SHAFT LH ?	1	2,118.60	2,118.60
OUTPUT SHAFT RH ?	1	2,118.60	2,118.60
RR INTEGRAL LINK ?	2	154.50	309.00
TRACK STRUT WITH RUBBER MOUNT ?	2	247.20	494.40
RR LH WISHBONE ?	1	617.95	617.95
RR RH WISHBONE ?	1	617.95	617.95
RR LH WHEEL CARRIER ?	1	1,328.45	1,328.45
RR RH WHEEL CARRIER ?	1	1,328.45	1,328.45
RR LH SWING PART ?	1	984.05	984.05
RR RH SWING PART ?	1	984.05	984.05
ALLOY RIM 81/2JX19 STY SPK366 SLA	2	1,422.30	2,844.60
ALLOY RIM 9JX19 STY SPK 366 SLA	2	1,564.55	3,129.10
REAR LH SPRING STRUT ?	1	1,239.05	1,239.05
REAR RH SPRING STRUT ?	1	1,239.05	1,239.05
ACTIVE STABILIZER BAR ?	1	3,482.05	3,482.05
FRT LH SPRING STRUT ?	1	1,610.15	1,610.15
FRT RH SPRING STRUT ?	1	1,610.15	1,610.15
ACTIVE STABILIZER BAR ?	1	3,374.90	3,374.90
LH ENGINE HOOD HINGE ?	1	121.05	121.05
RH ENGINE HOOD HINGE ?	1	121.05	121.05
ENGINE SUPPORT LH ?	1	1,301.75	1,301.75
ENGINE SUPPORT RH ?	1	1,301.75	1,301.75
FRT LEFT WHEELHOUSE TORN	1	2,103.05	2,103.05
FRT LEFT WHEELHOUSE TORN	1	2,103.05	2,103.05
FRT LH FENDER TORN	1	1,143.20	1,143.20
FRT RH FENDER TORN	1	1,143.20	1,143.20
SIDE PANEL BRACKET FRT LH 2 m	1	41.20	41.20
FRT RH SIDE PANEL BRACKET 2 m	1	41.20	41.20
FRT LH SIDE PANEL BRACKET 3 m	1	41.20	41.20
FRT RH SIDE PANEL BRACKET 3 m	1	41.20	41.20
FRT LH 1 SIDE PANEL BRACKET m	1	41.20	41.20
FRT RH 1 SIDE PANEL BRACKET m	1	41.20	41.20
BONNET bu	1	41.20	41.20
Set of mounting bumper front m	1	2,914.60	2,914.60
FRT BUMPER LOWER MOUNT CR	1	37.10	37.10
FRT BUMPER LH CONNECTOR dis	1	181.10	181.10
FRT BUMPER RH CONNECTOR dis	1	60.03	60.03
FRT BUMPER FLAP COVER SPRING CR	1	60.03	60.03
GRILLE AIR INTAKE CENTER mis	2	5.50	11.00
GRILLE AMOEK LH/RH mis	1	121.15	121.15
FRT BUMPER CARRIER bt	2	65.45	130.90
FRT BUMPER IMPACT ABSORBER TOP MIS	1	787.25	787.25
	1	114.75	114.75

T/Radio: Insured / Std / ...

Eng/No:
C/No:

Sum Insured:

Performance Motors Limited

Sime Darby Motors Company
Reg. No. 197401559W GST Reg. No M2-0020081-X
1-800-2255269

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62226
Date Estimated : 21/06/2022
Prepared By : Foong Shiuh Jye

Page No. : 5 of 9

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	640iA-C	135877

DESCRIPTION	QTY	PRIC	VALUE
DEFORMATION ELEMENT FRT LOWER RH <i>de</i>	2	116.90	233.80
LEFT FINISHER <i>?</i>	1	40.10	40.10
RIGHT FINISHER <i>?</i>	1	40.10	40.10
FRT BUMPER SPOILER <i>con</i>	1	82.85	82.85
FRT BUMPER TRIM PRIMED (PDC) <i>new TURN</i>	1	1,621.70	1,621.70
FRT BUMPER TOW HOOK COVER (PRIMED) <i>mis</i>	1	53.25	53.25
COVERING PRIMEND LH <i>mis</i>	1	53.25	53.25
COVERING PRIMEND RH <i>mis</i>	1	53.25	53.25
LH FOG LAMP COVER <i>mis</i>	1	95.40	95.40
RH FOG LAMP COVER <i>mis</i>	1	95.40	95.40
FRT LH GRILLE <i>mis</i>	1	169.50	169.50
FRT RH GRILLE <i>mis</i>	1	169.50	169.50
FRT BUMPER NO PLATE HOLDER <i>mis</i>	1	70.95	70.95
REARVIEW MIRROR EC/LED <i>?</i>	1	959.65	959.65
BONNET GAS STRUT <i>?</i>	2	139.85	279.70
FRT W/SCREEN (HUD) <i>con</i>	1	1,685.25	1,685.25
FRT W/SCREEN MOULDING (HUD) <i>ne</i>	1	258.65	258.65
BUMP STOP <i>ne</i>	10	3.30	33.00
TRIM PANEL DASHBOARD (SCHWARZ) <i>?</i>	1	5,081.05	5,081.05
RIGHT FRT HEAT INSULATION <i>de</i>	1	179.20	179.20
HEAT INSULATION <i>de</i>	1	77.70	77.70
Insulation front wall <i>?</i>	1	65.75	65.75
Insulation engine support RH <i>?</i>	1	95.60	95.60
Insulation engine carrier top <i>?</i>	1	77.70	77.70
LH SUPPORT <i>bt</i>	1	31.25	31.25
RH SUPPORT <i>bt</i>	1	31.25	31.25
CONNECTION TOP REAR <i>?</i>	1	349.55	349.55
FRT AIR DUCT <i>con</i>	1	357.65	357.65
SUPPORT LH <i>bt</i>	1	130.30	130.30
SUPPORT RH <i>bt</i>	1	130.25	130.25
JOINT UPPER FRONT <i>?</i>	1	188.25	188.25
CROSS BRACE REAR LH <i>?</i>	1	36.60	36.60
CROSS BRACE REAR RH <i>?</i>	1	36.60	36.60
CROSS BRACE FRT LH <i>?</i>	1	36.60	36.60
CROSS BRACE FRT RH <i>?</i>	1	36.60	36.60
COVER LEFT <i>?</i>	1	36.60	36.60
COVER RIGHT <i>?</i>	1	10.50	10.50
STIFFENING PLATE <i>?</i>	1	10.80	10.80
TORSION STRUT <i>?</i>	1	142.30	142.30
COVER WINDSHIELD <i>?</i>	1	132.50	132.50
FRT LH WHEEL ARCH COVER FRT SECTION <i>con</i>	1	59.75	59.75
FRT RH WHEEL ARCH COVER FRT SECTION <i>con</i>	1	143.35	143.35
AIR DUCT BRAKE LH/RH <i>?</i>	1	143.35	143.35
AIR DUCTING FOR AMOEK LH <i>?</i>	2	66.05	132.10
AIR DUCTING FOR AMOEK RH <i>?</i>	1	69.35	69.35
UNDERHOOD SHIELD FRT <i>?</i>	1	69.35	69.35
SEAL ENGINE BONNET FRT <i>ne</i>	1	207.30	207.30
SEAL HOOD SIDE <i>ne</i>	1	33.85	33.85
SUPPORT SEAL REAR LH <i>ne</i>	1	51.80	51.80
	1	258.90	258.90

Performance Motors Limited

Darby Motors Company
Reg. No. 197401559W GST Reg. No M2-0020081-X
1-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62226
Date Estimated : 21/06/2022
Prepared By : Foong Shiuh Jye

Page No. : 6 of 9

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMU3688G	WBALW72090DK15108	31/05/2012	640ia-C	135877

DESCRIPTION	QTY	PRIC	VALUE
SUPPORT SEAL BEAR RH ?	1	258.90	258.90
SEAL A-PILLAR ?	1	203.20	203.20
STRIP UPPER APRON ?	1	77.00	77.00
LH COLUMN A STRIP ?	1	97.00	97.00
STRIP COLUMN A RH ?	1	97.00	97.00
RAIN LIGHT SOLAR & FOGGING SENSOR ?	1	387.35	387.35
REPAIR KIT FOR LED MODULE ?	2	433.70	867.40
Left headlight by	1	2,832.60	2,832.60
Right headlight by	1	2,832.60	2,832.60
HEADLIGHT DRIVER MODULE AHL XENON L m	2	856.95	1,713.90
CONTROL UNIT XENON LIGHT m	2	885.25	1,770.50
LH FOG LIGHT LED m	1	467.55	467.55
RH FOG LIGHT LED m	1	467.55	467.55
BUMPER PDC SENSOR (CODED) - ELBOW m	4	371.20	1,484.80
DECOUPLING RING PDC TORQUE CONVERTE m	4	5.15	20.60
SET ADHESIVE PADS FOR ACE 2.0 m	1	37.35	37.35
SIDE VIEW CAMERA ?	2	701.45	1,402.90
(DG) CLEANER R1 (100ML) m	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) m	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) m	1	27.85	27.85

Total Parts : 127,941.26

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 22/06/22 @ 1510 Excess S\$ 600

Surveyor's Name RABUL Sign _____

Surveyor's Tel 96060688 Authorised Yes (X) No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 20-22 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	59,362.00
Parts	:	127,941.26
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	13,111.23
Grand Total	:	200,414.49

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SP0001 / PREMIUM AUTOCARE CENTRE [159938]
 DATE & TIME: 17/06/2022 18:00 (SGT)
 REPORTED BY: WONG KHONG SENG
 LOCATION: 1 (17/06/2022 18:00 (SGT))

Your NCD will be affected due to late reporting



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/06/2022 18:00 (SGT)
 Date of Accident 15/06/2022 03:00 (SGT)
 Exact Location of Accident Choa Chu Kang Rd, Singapore
 Additional Location Information ALONG CHOA CHU KANG RD
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMU3688G

INSURED/POLICYHOLDER

Is company? No
 Name Of Registered Owner LIM KUAN YIOU
 NRIC No S9511960C
 Email Address LIMKUANYIOU@HOTMAIL.COM
 Mobile Phone No (Phone) +65-96787030
 Alternative Phone No (Office) +65-9787030

VEHICLE PARTICULARS

Manufacturer BMW
 Model 640i
 Variant 640I 3.0 AT ABS D/AB HID DSC NAV HUD
 Exact purpose for which vehicle was being used at time of accident Private use
 Are you claiming under your own insurance policy for repair to your vehicle? Yes
 Vehicle Category Private car
 Transmission Auto
 CC 3000

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
 Type of Coverage Comprehensive
 Fleet Policy No
 Policy Number -
 Cover Note Number -

DRIVER

Name of Driver LIM KUAN YIOU
 NRIC No S9511960C



Date of Birth	17/03/1995
Occupation	Indoor
Date Of Driving Pass	25/06/2015
Driving experience	7 YEARS
Gender	Male
Mobile Number	(Phone) +65-96787030
Alt. Phone Number	(Office) +65-9787030
Email Address	LIMKUANYIOU@HOTMAIL.COM
Address	36 PAVILLION GROVE
Address complement	-
Postcode	658628
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN & POLICE REPORT.

LATE, DUE TO DELAY IN RESPONSE FROM TRAFFIC POLICE HQ.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Please refer to the sketch plan & police report.

Late, due to delay in response from Traffic Police HQ.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

17/6/2022 @ 1831



SINGAPORE POLICE FORCE



T/20220615/2015

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20220615/2015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/06/2022 09:09		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: LIM KUAN YIOU			Address: 36 PAVILION GROVE SINGAPORE 658628		
ID Type / ID No.: NRIC NO / S9511960C			Contact No.: Home/Office: Mobile: 96787030		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 17/03/1995	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: F&B DIRECTOR			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 15/06/2022 03:45	Type of Location:
Location: CHOA CHU KANG ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Lamp Post				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMU3688G	Car	BMW	640I 3.0 AT ABS D/AB HID DSC NAV HUD	Black	Totally Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMU3688G	ALLIANZ INSURANCE SINGAPORE PTE. LTD.	SP2001915279	31/05/2022	30/05/2023



**SINGAPORE
POLICE FORCE**



T/20220615/2015

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 3

Report No. T/20220615/2015

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM KUAN YIOU	ID No.	S9511960C
Related Vehicle	SMU3688G (Car)	Contact No.	96787030
Hospital/Clinic	CCK FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	15/06/2022	Date Discharge	15/06/2022
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

On the 15/06/2022 at about 0345hrs, I was driving vehicle SMU3688G along Choa Chu Kang Rd towards Bukit Batok Rd on lane 1. As I was too tired, I fell asleep while the vehicle was still moving. I did not realize that my car has mounted the curb and hit a lamppost, causing the lamppost to fall. The impact woke me up.

After the collision, I exited my vehicle to assess the damage caused. My car's front was badly damaged, and my car's airbag was deployed. I then dialed for the tow truck (HP: 85888877) but I was not sure if the tow truck had come down. Another tow truck drove past the accident scene and rendered his assistance. As this was my first time experiencing an accident, I was not sure what to do. As my place of residence was nearby, I returned home to seek assistance from my parents. My parents told me that they would go down to the scene to check on the vehicle and passed their car to me, for me to seek medical treatment at the clinic. I left the scene, with no one guarding the vehicle.

As I was too tired, I slept in the car which was within the estate boundary until 0700hrs on the same day. After I woke up, I proceeded to CCK Family Clinic to sought medical treatment and was given a 2-day MC from 15/06/2022 to 16/06/2022.

I wish to state that my car does not have an in-car camera.



SINGAPORE POLICE FORCE



T/20220615/2015

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3

Report No. T/20220615/2015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

J /

SGT 2 CAI XIN YU

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Other MUHAMMAD NOOR BIN ABDUL
RAHMAN

Contact No.: 65476219

Signature Of Informant:

Date/Time:

15/06/2022 09:09

Classification Of Case:

NP168

65476219

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S9511960C**

Name:

LIM KUAN YIOU

Birth Date: **17 Mar 1995**

Issue Date: **14 May 2019**



002933480G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S9511960C**



Name

LIM KUAN YIOU

林冠佑

Race

CHINESE

Date of birth

17-03-1995

Country/Place of birth

SINGAPORE

Sex

M

S9511960C

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg **25 Jun 2015**

NP 428A



Licence No: S9511960C

6207487



NRIC No. **S9511960C**



Date of issue

14-05-2019

Address

**36 PAVILION GROVE
SINGAPORE 658628**

CCK FAMILY CLINIC		Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	15/06/2022	Date Discharge	15/06/2022
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

On the 15/06/2022 at about 0345hrs, I was driving vehicle SMU3688G along Choa Chu Kang Rd towards Bukit Batok Rd on lane 1. As I was too tired, I fell asleep while the vehicle was still moving. I did not realize that my car has mounted the curb and hit a lamppost, causing the lamppost to fall. The impact woke me up.

After the collision, I exited my vehicle to assess the damage caused. My car's front was badly damaged, and my car's airbag was deployed. I then dialed for the tow truck (HP: 85888877) but I was not sure if the tow truck had come down. Another tow truck drove past the accident scene and rendered his assistance. As this was my first time experiencing an accident, I was not sure what to do. As my place of residence was nearby, I returned home to seek assistance from my parents. My parents told me that they would go down to the scene to check on the vehicle and passed their car to me, for me to seek medical treatment at the clinic. I left the scene, with no one guarding the vehicle.

As I was too tired, I slept in the car which was within the estate boundary until 0700hrs on the same day. After I woke up, I proceeded to CCK Family Clinic to sought medical treatment and was given a 2-day MC from 15/06/2022 to 16/06/2022.

I wish to state that my car does not have an in-car camera.

Fire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 960C

Vehicle Details

Vehicle No.: SMU3688G

Vehicle to be Exported: Yes

Intended Deregistration Date: 22 Jun 2022

Vehicle Make: B.M.W.

Vehicle Model: 640i 3.0 AT ABS D/AB HID DSC NAV HUD

Primary Colour: Black

Manufacturing Year: 2011

Engine No.: 15777825N55B30A

Chassis No.: WBALW72090DK15108

Maximum Power Output: 235.0 kW (315 bhp)

Open Market Value: \$76,245.00

Original Registration Date: 31 May 2012

First Registration Date: 31 May 2012

Transfer Count: 1

Actual ARF Paid: \$76,245.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2032

COE Category: E - Open Category

COE Period(Years): 10

PQP Paid: \$93,644.00

COE Rebate Amount: \$93,065.00

Total Rebate Amount: \$93,065.00

The information contained herein is correct as at 22 Jun 2022

OK

BMW 6 Series 640i Coupe Sunroof (COE till 02/2032)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$143,000		
Depreciation 	\$14,750 /yr	Reg Date 	15-Jun-2012 (9yrs 8mths 6days COE left)
Mileage	117,000 km (11.7k /yr)	Manufactured 	2011
Road Tax	\$2,362 /yr	Transmission	Auto
Dereg Value 	\$78,110 as of today (change)	OMV 	\$71,551
COE 	\$80,583	ARF	\$71,551
Engine Cap	2,979 cc	Power	235.0 kW (315 bhp)
Curb Weight 	1,660 kg	No. of Owners 	2
Type of Vehicle	Sports Car		