

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS6/AIS22005936/UVY3M4**Date:** 01/07/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPMF1000000459
Claimant Vehicle No :	SLF3008K	Insured Vehicle No :	XE4092Y
Date of Loss:	18/06/2022	Nature of Claim:	TP
		Claim No:	800SWAISCL2022-0131FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3008K	Engine No:	R16A13006751
Make & Model:	HONDA CIVIC, 2.0 (A)	Chassis No:	JHMFD46208S202327
Reg. Date:	06/09/2008 (Man. Year: 2008)	Odometer:	189611 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	871.20	798.60	72.60	8.33
Miscellaneous Items	650.00	650.00	0.00	0.00
Labour	1,410.00	920.00	490.00	34.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,931.20	2,368.60	562.60	19.19
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,931.20	1,650.00	1,281.20	43.71
+ GST 7.00/7.00% (S\$)	205.18	115.50	89.68	43.71
Nett Amount (S\$)	3,136.38	1,765.50	1,370.88	43.71

INSPECTION

Date of Assignment:	21/06/2022 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	22/06/2022 Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT BUMPER	650.00	650.00
			Sub Total (\$\$)	650.00
				650.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	4 WHEEL ALIGNMENT	New	80.00	0.00
3	LABOUR CHARGE	New	600.00	400.00
4	SPRAY PAINTING	New	700.00	500.00
			Gross Labour Cost (\$\$)	1,410.00
				920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >