

The Motor Claims Department

M/s Great American Insurance Company, Singapore Branch
3 Temasek Avenue, #16-01
Centennial Tower
Singapore 039190

File No : SH/2022/147/06/024/OD
Date : 21-June-2022



Estimated cost of repair for vehicle no :
Policy no: MOMVC000008202-02-000

GBF551X Fiat Doblo

Accident Date: 16.06.2022

*Not Notified
11 Pm @ 5300h
Pulverized After Paint
Ex TRA 6 days*

Description	Quantity	Cost Price
Bonnet	1	\$ Bu 380.00 ✓
RH bonnet hinge	1	\$ R 120.00 X
LH bonnet hinge	1	\$ n 120.00 X
Bonnet lock	1	\$ D/I 80.00 ✓
Front grille	1	\$ n 280.00 ✓
Front grille emblem	1	\$ CM 120.00 ✓
RH head lamp	1	\$ My CM 280.00 ✓
LH head lamp	1	\$ n 280.00 ✓
LH front fender	1	\$ Bu 230.00 ✓
LH front fender wheel cowling	1	\$ CM 280.00 ✓
LH front fender wheel cowling clips (1 set)	1	\$ n 18.00 ✓
Front bumper	1	\$ Bu 450.00 ✓
Front bumper centre grille	1	\$ D/I 280.00 ✓
Front bumper sponge	1	\$ CM 150.00 ✓
Front bumper reinforcement	1	\$ n 250.00 ✓
RH Front bumper retainer	1	\$ D/I 55.00 ✓
LH Front bumper retainer	1	\$ D/I 55.00 ✓
Front bumper lower reinforcement	1	\$ R 130.00 X
Front bumper centre plastic reinforcement	1	\$ n 75.00 X
Front support panel	1	\$ Bu 250.00 ✓
RH head lamp inner panel	1	\$ R 160.00 X
LH head lamp inner panel	1	\$ R 160.00 ✓
Wiper water tank	1	\$ n 290.00 X
AC condensor	1	\$ n 380.00 ✓
AC condensor pipe inlet	1	\$ n 140.00 X
AC condensor pipe outlet	1	\$ n 160.00 X
AC condensor upper air guide	1	\$ n 130.00 X
AC condensor surround air guide	1	\$ n 250.00 ✓
Radiator	1	\$ n 360.00 X
Radiator fan assembly	1	\$ CM 350.00 ✓
Radiator spare tank	1	\$ n 140.00 X
Turbo intercooler	1	\$ n 480.00 X
		\$ 6,883.00
	Add 15%	\$ 1,032.45
		\$ 7,915.45



Front number plate

Engine coolant

LH front door company sticker

1	S. nett	\$	45.00	✓
1	S. nett	\$	30.00	✓
1	S. nett	\$	25.00	✓

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality

\$ 120.00 100d

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair LH front door, RH front fender, bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment

\$ 750.00 60d

To spray paint affected front and inner damaged portion inclusive of preparatory works and material

\$ 1,250.00 100d

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 80.00 20d

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ ~ 180.00 X

\$ 10,395.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: