



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22005939/Rny3e2 Date: 13/01/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 6835D	Veh. Inspected	SLK 9253C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22001900MFCV	Excess (\$)	0.00	
Assign From	CAROLINE CABRERA	Assign Date	22/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS CL 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MR053REH104562068	Colour	GREY	
Odometer	214876 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	6 mm	
L/H Front Tyre	205/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	21/06/2022	Inspection Date	22/06/2022	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	