SS. RECABY: STOVE 1 """	1
A	SSIGNMENT. OAL 1919-17
rom:Date:	Veh No: SLU 9610 C Yr Regn: 1912/17
slimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry /- Taxl / Prime Mover /
D TE WS (TP RES) OD RES ! EVA ! INV ! MY	Truck/Trailer or
o Inspect Vehicle No:	Make: 10009 Shuttle c.c 1096 AC: Insured / Std / NI / NA
t Workshop m/s	Colour, Silver A/C: Insured / Std / NI / NA
	Sp.Reading TRAVY
nsured:	Eng/No:
rollcy No.	CNO: (11/2/5/0
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/Rim (STD A/Rim of
	Tyre Size: F: 185/60/715
(Policy Condition)	R: //
Remark: The veh had commenced its N/S	O/S BS I DUN I EXNOVA I GY I FS I LIZA I MIGI OHTSU I PIR I SUMI
repair at the time of inspection.	TOYO I YOKO or ·
Bal. or Market Value:	Fron! mm
IDAC Accident Roort: Consistent?: Yes or No	UBal. K mm
GIA / PR Seen: Consistent? : Yes or No .	001 00/01/01
Est Repairs: days Res.: Yes or No	D.O.A. 11 6 12
Lum Sum: % · 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA REV REP. 24 HRS	
	The UIC I Chassis frame I Body Structure affected due to collision.
Date:Person Contacted:	
Date / Time Action / Instruction N/ / 75	
	Days Of Repair:
Osterime, File Pass to? : Prell. Report	Resurvey No. of Trip: Survey Fee:
Final Report	. Transportation:
Date/Time, File Return to?	Add Fee: Site Insp (\$) s+Rs_si
2)	: Interview (\$) Photos
	:Tech, Invs (\$) Others
Repair Formal :	:Weelend (\$)
Lump Sun / L.B. k. (#	TOTAL
•	

Auto Insure Pte. Ltd 6 Marsiling Lane 739145

Insurer Reference: SLU9610C

Repairer Reference: M5282/SLU9610C Date calculated: 20/06/2022 7:22 PM

Full Report Registration: SLU9610C Printed: 20/06/2022 7:22 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference:

Marvyn Chua **SLU9610C**

Currency: Date of Incident: Hire Car Start:

Hire Car End:

SGD 11/06/22

Estimated Repair Time: Actual Repair Days:

6

HONDA

STREAM

SLU9610C

78584

GP71121398

LS 35 36 01

Vehicle Details

Vehicle

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer: **Model Specs**

TWO COAT METALLIC

5600 CCKK)
92/6/22, 3.0002
Whe h

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before their spray painting
- To display damaged part(s) during resurvey
- · Farts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is all swell
- . Supplementary item(s) must be resonated and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Tyres Condition

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Tyre Brand

mm

Middle), mm

Tread (Spare), mm

ı	L	a	b	0	u	r

Labour	Time Base 10 WU/h	Price = 42.	00 SGD/h
Code	Description	wu	Price SGD
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	8.40
NO NUMBER	BUMPER CARRIER REAR RUST PROOFING	1.0	4.20
NO NUMBER	R + R REAR DOOR	3.0	12.60
68100-S7A)	RENEW TAILGATE (REMOVED) INCLUDES: R + R REAR WINDOW, REAR WIPER, REAR WIPER MOTOR, LOCK, NUMBER PLATE LAMPS AND TAILGATE TRIMS	52.0	218.40
NO NUMBER	RENEW L/INNER SIDE PANEL CONNECTION	20.0	84.00
NO NUMBER	R + R REAR END PANEL ATTACHED PARTS INCLUDES: R + R BUMPER, TAIL LAMP, BOOT TRIM, BOOT FLOOR TRIM, REAR PANEL TRIM, BOOT LOCK AND SEAL	35.0	147.00
66100-S7A	RENEW REAR END PANEL CPL	37.0	155.40
17500-S5A	R + R FUEL TANK	15.0	63.00
04655-S7A	RENEW REAR FLOOR CPL	25.0	105.00
NO NUMBER	R + R REAR SEAT	2.0	8.40
NO NUMBER	R + R LEFT CENTRE SEAT	2.0	8.40

Audatex System Using Manufacturer Times

Page 2 of 5

PRINT DATE 20/06/2022



de	Description				WU	Price SGI
NO NUMBER	R + R RIGHT CENTRE SEAT				2.0	8.40
4130-S7A	R + R L/UPPER C-PILLAR TR	IM			4.0	16.80
640	REAR BUMPER SUPPORT CA					
	Labarra Cank			Hrs	WU	
	Labour Cost Panel / Mechanical Labou	ır		19.70	197.0	827.4
						827.4
	Total of Labour					
Paint				71.	an Bacic	10 WU/h
Paint Work		SYSTEM AZT		111	WU	Price SGI
ode	Description - TWO COAT	METALLIC			WU	FIICE DO.
	THE PART OF MENT PART	DAINTING			14.0	
	REAR PANEL CPL NEW PART	PAINTING			14.0	
	TAILGATE NEW PART PAINT	NG			4.0	
	L/R LAMP PANEL SURFACE PAIN	T			11.0	
	BOOTFLOOR SURFACE PAIN					
Paint Materia						Price SG
Code	Description					13.2
2711	REAR PANEL CPL NEW PART	PAINTING				35.0
AND RESIDENCE AND ADDRESS OF THE PARTY OF	TAILGATE NEW PART PAINT	ING				2.7
2931	LIR LAMP PANEL SURFACE F	AINT				34.8
3571 3900	BOOTFLOOR SURFACE PAIN	T				•
	Labour Cost - Paint		cop //s	Hrs	WU	Price SGI
	Factor		42.00 SGD/h		43.0	
	Time Paint			2.10	21.0	88.2
	Preparation Main Work Meta	l	10 WU/h	6.40	64.0	268.8
	Total		10 00711			
						Price SGI
	Material Cost - Paint					48.2
	New Part Painting					37.6
	Surface-/Blend Paint					18.1
	Material-constant Metal					103.9
	Total					
Spare Part	s			ricas as	at 2015	5-06-01/0
		Part Number	Part Source	ices as		Price SGI
Code	Description	Part Number	0			210.0
2977	BOOT/TAILGATE LOCK	74800S7AE01	Original	1		130.0
2944	BOOT/TAILGATE SEAL	74440S7A000		PARTY		940.0
3900	BOOTFLOOR	04655S7A307ZZ	Original y			25.0
1002	BUMPER COVER LH	REAR	Original X			25.0
1003	BUMPER COVER RH	REAR	Original &			55.0
1004	BUMPER REFLECTOR LH	REAR	Original X			55.0
1005	BUMPER REFLECTOR RH	REAR	Original V			70.0
1008	EMBLEM (HYBRID)	REAR TAILGATE	Original / /			70.0

Code					
	and the second second	Part Number	Part Source		Price SGD
	Description	Part Number	- 1-1-01 / //		Seco
1007	EMBLEM (SHUTTLE)	REAR TAILGATE	Original -		100.00
4985	END PANEL TRIM	84640S7AJ01ZA	Original X		15.00
2617	L/R INN BUMPER BRKT	71555S7A000	Original X		45.00
3571	L/R LAMP PANEL	63730S7AG00ZZ	Original X		190.00
2619	L/R OUT BUMPER BRKT	71598S7A003	Oligina		25.00
1006	LOGO (HONDA)	REAR TAILGATE	Original X		25.00
4907	LOWER TAILGATE TRIM	84440S7AJ01ZA	Original X		25.00
2620	R/R OUT BUMPER BRKT	71593S7A003	Original X		25.00
2583	REAR BUMPER	71501S7A000ZE	Original / 00		820.00
2640	REAR BUMPER SUPPORT		Original X		0.00
2711	REAR PANEL CPL	66100S7AG01ZZ	Original & / DD		410.00
3941			Original		95.00
The state of the s	RR FLOOR RR C-MEMBER		Original X		600.00
2931	TAILGATE	68100S7AG11ZZ	Original > 00		
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Savings				3,945.00
u: Used parts	Subtotal				3,343.00
a. osca pares	Total	on the state of th			3,945.00
Extras					
Code	Description				Price SGD
02 - mm2		d 11		200	175.55
1000	PARKING SENSORS REAR	Shots		The second secon	250.00*
1001	BUMPER CLIPS REAR	nc "		30	50.00*
1009	END PANEL SEALANT REAR			80	35.00*
	Total Extras				335.00
Final Calcul	ation			SGD	SGD
				300	300
Parts					300
Parts Total Parts				3,945.00	
Total Parts	1\deline				3,945.00
Total Parts Labour Time	Base 10 WU/h				
Total Parts Labour Time Total 197.0	WU X 42.00 SGD/h				
Total Parts Labour Time	WU X 42.00 SGD/h			3,945.00	3,945.00
Total Parts Labour Time Total 197,0 Total of Labou	WU X 42.00 ŚGD/h r			3,945.00	
Total Parts Labour Time Total 197,0 Total of Labou Additional Cos	WU X 42.00 ŚGD/h r			3,945.00	3,945.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing	WU X 42.00 ŚGD/h r ts			3,945.00	3,945.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h			3,945.00 827.40	3,945.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h			3,945.00	3,945.00 827.40
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h			3,945.00 827.40	3,945.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h onal Costs			3,945.00 827.40	3,945.00 827.40
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h onal Costs			3,945.00 827.40	3,945.00 827.40 12.60
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h			3,945.00 827.40 12.60	3,945.00 827.40 12.60
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6	WU X 42.00 ŚGD/h r ts WU X 42.00 SGD/h onal Costs			3,945.00 827.40	3,945.00 827.40 12.60
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h 64.0 WU X 42.00 SGD/h			3,945.00 827.40 12.60	3,945.00 827.40 12.60
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h			3,945.00 827.40 12.60 268.80	3,945.00 827.40 12.60
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost Total Paint Inc Repair Cost Ex	WU X 42.00 SGD/h r ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h 64.0 WU X 42.00 SGD/h luding Material			3,945.00 827.40 12.60 268.80	3,945.00 827.40 12.60 335.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost Total Paint Inc Repair Cost Ex GST (+7.00%	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h 64.0 WU X 42.00 SGD/h luding Material cludes GST			3,945.00 827.40 12.60 268.80	3,945.00 827.40 12.60 335.00
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost Total Paint Inc Repair Cost Ex	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h 64.0 WU X 42.00 SGD/h luding Material cludes GST			3,945.00 827.40 12.60 268.80	3,945.00 827.40 12.60 335.00 372.79 5,492.79
Total Parts Labour Time Total 197.0 Total of Labou Additional Cos Rustproofing Rate 3.0 Total Of Additi Total Of Extras Paint Work Ti Labour Cost 6 Material Cost Total Paint Inc Repair Cost Ex GST (+7.00%	WU X 42.00 SGD/h ts WU X 42.00 SGD/h onal Costs me Base 10 WU/h 64.0 WU X 42.00 SGD/h luding Material cludes GST			3,945.00 827.40 12.60 268.80	3,945.00 827.40 12.60 335.00 372.79 5,492.79 384.50



comments
* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Audatex System Using Manufacturer Times

Page 5 of 5

PRINT DATE 20/06/2022



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 3. Information provided must be as truthful and accurate as possible, Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

13/06/2022 10:16 (SGT) **Date of Submission** 11/06/2022 11:50 (SGT) **Date of Accident** JURONG WEST CENTRAL 1 TURNING INTO JURONG WEST ST Jurong West Central 1, Singapore **Exact Location of Accident** Additional Location Information 64 Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

Honda

SLU9610C Vehicle Registration Number

INSURED/POLICYHOLDER

No Is company? YAP SHI YUAN Name Of Registered Owner SXXXX559Z NRIC No yapshiyuan@yahoo.com.sg **Email Address** (Phone) +65-96224795 Mobile Phone No +65-96224795 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Shuttle Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category Auto Transmission 1496 CC

INSURANCE COMPANY

Auto & General Insurance (Singapore) Pte. Limited. Name of Insurance Company Comprehensive Type of Coverage No Fleet Policy P10280315R02 **Policy Number** Cover Note Number

DRIVER

CHANG MEI HUA Name of Driver



Page 1 of 19



SXXXX277G NRIC No 23/11/1982 Date Of Birth Indoor 22/09/2008 Occupation 13 YEARS AND 9 MONTHS **Date Of Driving Pass Driving experience** Female (Phone) +65-97915962 Gender Mobile Number zumikachang@gmail.com Alt. Phone Number BLK 183B BOON LAY AVE #12-724 **Email Address** Address Address complement 642183 Postcode No Is the driver the policyholder? If No, Relationship of the Driver with the Insured Spouse No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 NA Name Male Gender PASSENGER 2 NA Name Male Gender DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 11/6/2022 AT ABOUT 1150. I WAS TRAVELLING ALONG JURONG WEST CENTRAL 1 TURNING INTO JURONG WEST ST 64.WHILE WAITING THE MAIN ROAD TRAFFIC TO CLEAR, WHEN SUDDENLY I FELT AN IMPACT FROM MY REAR AND REALISED THAT VEHICLE B HAD COLLIDED ONTO MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

Yes

FILE IS TOO LARGE

No



Page 2 of 19




DETAILS OF OTHER VEHICLE PROPERTY 1

picle Registration Number	SLJ3281R
picle Registraturer venicle Manufacturer venicle Model	
vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	CHUA KIM HONG
NRIC No	SXXXX269J
Contact Number	(Phone) +65-93669710
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A PLU THIOC

B: MJ3081R



					OF THE A			adling	alon	g jutons	g we	ct cen	tral	1 10	ming
p40	Jua	ng_	M	St 5t	64-	While	uating	the	hair	had	that	fic t	0 (lar i	ulun
tuddi	niy	1	felt	an	impact	flom	my	tear	and	tealised	that	which	В	collia	ud
onto	my	veh	idi.												
	_														
		_													

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Date & Time:

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:



	oneMotoring
4	onelvie

PARF/COE Rebate for Registered Vehicle Owner Particulars		
particulars vehicle Owner D Type: owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	559Z	
	SLU9610C	
to to he Exported.	No	
Vehicle to be Intended Deregistration Date:	18 Jun 2022	-
Vehicle Make:	HONDA	
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO	
primary Colour:	Silver	
Manufacturing Year:	2017	
Engine No.:	LEB6326388	
Chassis No.:	GP71121398	
Maximum Power Output:	101.0 kW (135 bhp)	
Open Market Value:	\$21,183.00	
Original Registration Date:	19 Dec 2017	
First Registration Date:	19 Dec 2017	
Transfer Count:	O	
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	18 Dec 2027	
PARF Eligibility Explity Settlements Intended COE Rebate Details	\$3,750.00	
COE Expiry Date:	18 Dec 2027	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
	10	
COE Period(Years):	\$53,711.00	
QP Paid:	\$29,541.00	
COE Rebate Amount:	\$33,291.00	-
Total Rebate Amount:		

The information contained herein is correct as at 18 Jun 2022