

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5377P

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident : 17/06/2022

Third Party Insurer :

Date of Registration:

21 JUN 2022

AAD2206-

PART		LIST	
1	COVER, REAR BUMPER	\$	442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$	15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$	576.30 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	116.50 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	117.70 X
1	PANEL SUB-ASSY, BACK DOOR	\$	1,147.80 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	925.60 X
1	COVER, FLOOR UNDER, NO.2 RH	\$	241.90 X
1	COVER, REAR FLOOR CTR	\$	229.90 X
1	COVER, DECK TRIM, REAR	\$	126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30 X
1	SEAL, REAR BUMPER SIDE, RH	\$	88.50 X
1	STAY ASSY, BACK DOOR, LH	\$	242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	61.00 X
1	REAR TAILGATE TOYOTA LOGO	\$	47.90 ✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	54.60 ✓
1	REAR TAILGATE WORDING 'HYBRID'	\$	54.60 ✓
TOTAL		\$	5,776.00
25%		\$	1,444.00
		\$	4,332.00

Special Nett

1SET PARKING AID	\$	700.00 220.00 ✓
1SET REAR BUMPER CLIP	\$	95.00 60.00 ✓
2 WINDSCREEN SEALANT	\$	150.00 X
1 WINDSCREEN MOULDING	\$	200.00 X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00 X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00 30.00 ✓
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00 30.00 ✓
1 REAR BUMPER PROTECTOR	\$	180.00 X
1SET REAR BUMPER RETAINER CLIP	\$	85.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5377P

AAD2206-

1 END PANEL TRIM CLIP	\$	nn 65.00	X
TOTAL	\$	1,765.00	

TOTAL PARTS \$ 6,097.00**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 300.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	4401
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	151

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-

SHD5377P

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 X**TOTAL** \$ **8,920.00****Over All Total** \$ **15,017.00****(PART-BY-PART) Repair Days****25 DAYS***2 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: