



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP667H HONDA HRV

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	\$ 1,500.00	de✓
2	1	Front bumper right bracket	\$ 85.00	de✓
3	1	Front bumper right side retainer	\$ 85.00	de✓
4	1	Front bumper reinforcement	\$ 380.00	bt✓
5	1	Front bumper lower grille	\$ 450.00	xnn
6	1	Front bumper tow cover	\$ 65.00	de✓
7	1	Front bumper lower garnish	\$ 125.00	xnn
8	1	Front bumper lower lip	\$ 450.00	xnn
9	1	Front grille assy	\$ 395.00	cra✓
10	1	Front grille emblem	\$ 88.30	nec✓
11	1	Front grille chrome moulding	\$ 585.40	xnn
12	1	Front bonnet assy	\$ 1,800.00	XR
13	1	Front bonnet hinges	\$ 98.60	xnn
14	1	Front bonnet rubber	\$ 280.00	xnn
15	1	Front bonnet inner board	\$ 381.50	xnn
16	1	Front support panel assy	\$ 898.30	XR
17	1	Front support panel top garnish cover	\$ 291.50	xnn
18	1	Front support panel rubber stopper	\$ 60.00	xnn
19	1	Front right headlamp	\$ 1,915.60	cra✓
20	1	Front right headlamp silver trim lining	\$ 164.80	nec✓
21	1	Front right headlamp bracket	\$ 197.50	xnn
22	1	Front right fender assy	\$ 682.30	XR
23	1	Front right fender inner cowl	\$ 188.90	xnn
24	1	Front froglight	\$ 295.90	cra✓
25	1	Front froglight casing	\$ 160.80	de✓
26	1	Water tank		xnn
		Sub-total	\$ 11,624.40	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP667H HONDA HRV

			Estimated
No	Qty	Parts Description	Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips	\$ 50.00 30 nec ✓
2	6	Front bumper lower grille clips	\$ 30.00 xnn
3	8	Front fender inner board clips	\$ 30.00 xnn
4	6	Front grille chrome moulding clips	\$ 30.00 nec ✓
5	6	Front grille clips	\$ 20.00 xnn
6	1	Front windscreen glass sealant	\$ 80.00 xnn
7	6	Front right fender inner cowling clips	\$ 30.00 xnn
8	1	Front right quarter glass sealant	\$ 60.00 xnn
9	1	Front right sport rim	\$ 850.00 xnn
10	10	Front right door inner board clips	\$ 30.00 xnn
11	8	Front support panel top garnish clips	\$ 30.00 xnn
12	1	Front no plate with garnish	\$ 80.00 xnn
<u>Special Nett Items</u>			\$ 1,320.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP667H HONDA HRV

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 2,000.00 700
2	To putty and spray painting front portion.	\$ 2,000.00 700
3	To check wiring and focus front headlamp.	\$ 60.00 30
4	To apply anti rust proofing to front affected area.	\$ 120.00 30
5	To remove and install front windscreen glass to facilitate the repair.	\$ 140.00 xnn
6	To remove and install front right undercarriage parts.	\$ 350.00 xnn
7	To balance front right wheel.	\$ 50.00 xnn
8	To conduct wheel alignment.	\$ 120.00 xnn
9	To remove and install rear right undercarriage parts	\$ 350.00 xnn
10	To remove and install front bonnet lock mechanism assy.	\$ 60.00 xnn
11	To check door central locking for function.	\$ 60.00 xnn
12	To putty and spray painting	\$ 500.00 xnn
13	To check leaking, remove and install aircon to facilitate the repair and refill gas	\$ 350.00 xnn
14	To check coolant and water system the leaking	\$ 200.00
Total labour :		\$ 6,360.00

Total parts : #REF!

Total labour : 6,360.00

Total repair cost : #REF!

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 97495749, 22/6/22

lumpsum repair

Resurvey after repair

5 days



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP667H HONDA HRV Additional Parts

No	Qty	Parts Description	Estimated Parts Price
1	1	Front top garnish cover	\$ 225.00 xnn
2	1	Front support side garnish	\$ 155.60 xnn
3	1	Headlight lower bracket-broken	\$ 187.50 cra ✓
4	1	Radiator support frame	\$ 1,280.00 XR
5	1	Condenser unit	\$ 1,600.00 xnn
6	1	Front righr side lower tray	\$ 195.60 xnn
		Sub-total	<u>\$ 3,643.70</u>

SMP667H HONDA HRV Additional Special Nett Item

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Lower lip clips	\$ 60.00 xnn
2	6	Wheel arch clips	\$ 40.00 20 nec ✓
3	8	Front side lower tray clips	\$ 40.00 xnn
4	4	Original coolant	\$ 160.00 xnn
		Special Nett Items	<u>\$ 300.00</u>