



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMP667H HONDA HRV

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 2,000.00
2	To putty and spray painting front portion.	\$ 2,000.00
3	To check wiring and focus front headlamp.	\$ 60.00
4	To apply anti rust proofing to front affected area.	\$ 120.00
5	To remove and install front windscreen glass to facilitate the repair.	\$ 140.00
6	To remove and install front right undercarriage parts.	\$ 350.00
7	To balance front right wheel.	\$ 50.00
8	To conduct wheel alignment.	\$ 120.00
9	To remove and install rear right undercarriage parts	\$ 350.00
10	To remove and install front bonnet lock mechanism assy.	\$ 60.00
11	To check door central locking for function.	\$ 60.00
12	To putty and spray painting	\$ 500.00
13	To check leaking, remove and install aircon to facilitate the repair and refill gas	\$ 350.00
14	To check coolant and water system the leaking	\$ 200.00
Total labour :		\$ 6,360.00

Total parts : #REF!

Total labour : 6,360.00

Total repair cost : #REF!