



簡 福 星 摩 工 廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12 Singapore 610147
Tel : (65) 6747 9560, 6858 2126, 6858 4361
Fax : (65) 6748 1096 6281 8428
E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMFG22005170	Date of Loss:	20/06/2022
Vehicle Reg. No.:	GBJ1728B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HWA SENG BUILDER PTE LTD		
Make/Model:	KIA K2500, 2.5 D 6M/T (M)	Vehicle Reg. Date:	24/01/2019
Vehicle Colour:	WHITE		
Engine No:	D4CBJ699407	Chassis No:	KNCSJX76LK7327553
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	1,535.60
Miscellaneous Items	40.00
Labour	630.00
Paintwork Labour	450.00
Towing	0.00
Calculated Gross Total (S\$)	2,655.60
- Excess (S\$)	500.00
(S\$)	2,155.60
+ GST 7.00% (S\$)	150.89
Nett Amount (S\$)	2,306.49

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 21 Jun 2022)
Parts: N/A KIA K2500 2.5 D 6M/T (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	*175.00 F
2	1		*FRONT BONNET LOCK	0.00	0.00	*20.00 F
3	1		*FRONT BONNET EMBLEM	0.00	0.00	*35.00 F
4	1		*FRONT GRILLE	0.00	0.00	*115.00 F
5	1		*FRONT HEADLAMP RH	0.00	0.00	*165.00 F
6	1		*FRONT HEADLAMP LH	0.00	0.00	*165.00 F
7	1		*FRONT BUMPER	0.00	0.00	*150.00 F
8	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*140.00 F
9	1		*FRONT BUMPER LOWER GRILLE TOP	0.00	0.00	*28.00 F
10	1		*FRONT BUMPER LOWER GRILLE LOWER	0.00	0.00	*28.00 F
11	1		*FRONT BUMPER FOGLAMP COVER LH	0.00	0.00	*15.00 F
12	10		*FRONT BUMPER CLIP	0.00	0.00	*25.00 F
13	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	*15.00 F
14	1		*FRONT WIPER PANEL	0.00	0.00	*165.00 F
15	1		*WASHER TANK	0.00	0.00	*130.00 F
16	1		*SPARE TANK	0.00	0.00	*25.00 F

F=Franchise part.

Sub Total (S\$)	1,396.00
+ Margin on L,N Items 10.00% (S\$)	139.60
Total Parts (S\$)	1,535.60

Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	40.00
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	450.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	580.00
Gross Labour Cost (S\$)			1,080.00

Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thruon
82235767
24/6/22 1400
OP: EXCESS TBC
not authorised
P/P 1 day swp