

简福星摩哆工廠
KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

TEL: 67479560, 68582126, 68584361

FAX: 67481006, 62818428

ERGO INSURANCE PTE LTD

8 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER 3

SINGAPORE 038988

VEHICLE NO. : GBJ1728B

ACCIDENT DATE : 20-06-2022 07:45

THIRD PARTY REF. : 199200384Z

INVOICE NO : TEST

DATE : 28-06-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE GBJ1728B KIA K2500 6MT

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BONNET	160.00
1	FRONT BONNET EMBLEM	40.00
1	FRONT BUMPER	150.00
1	FRONT BUMPER LOWR GRILLE TOP	28.00
1	FRONT BUMPER LOWER GRILLE LOWER	28.00
1	FRONT BUMPER FOGLAMP COVER LH	15.00
10	FRONT BUMPER CLIP @ 2.50	25.00
1	FRONT NUMBER PLATE GARNISH	15.00
1	WASHER TANK	40.00
		<u>501.00</u>
ADD 10 %		50.10
TOTAL (A)		<u>551.10</u>

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	30.00
TOTAL (C)		<u>30.00</u>

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	400.00

1/2

VEHICLE NO. : GBJ1728B
ACCIDENT DATE : 20-06-2022 07:45
THIRD PARTY REF. : 199200384Z

<u>QTY</u>	<u>PARTS DESCRIPTION</u>
1	SPRAY PAINTING CHARGES

<u>AMOUNT (SG\$)</u>
400.00

TOTAL (D)	820.00
TOTAL REPAIR COST :	1401.10
G S T % :	63.08
EXCESS AMOUNT :	500.00
INVOICE AMOUNT :	964.18

2/2

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 21 Jun 2022)

Parts: N/A KIA K2500 2.5 D 6M/T (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	160	*175.00 F
2	1		*FRONT BONNET LOCK	0.00		*20.00 F
3	1		*FRONT BONNET EMBLEM	0.00	40	*35.00 F
4	1		*FRONT GRILLE	0.00		*115.00 F
5	1		*FRONT HEADLAMP RH	0.00		*165.00 F
6	1		*FRONT HEADLAMP LH	0.00		*165.00 F
7	1		*FRONT BUMPER	0.00		*150.00 F
8	1		*FRONT BUMPER REINFORCEMENT	0.00		*140.00 F
9	1		*FRONT BUMPER LOWER GRILLE TOP	0.00		*28.00 F
10	1		*FRONT BUMPER LOWER GRILLE LOWER	0.00		*28.00 F
11	1		*FRONT BUMPER FOGLAMP COVER LH	0.00		*15.00 F
12	10		*FRONT BUMPER CLIP	0.00		*25.00 F
13	1		*FRONT NUMBER PLATE GARNISH	0.00		*15.00 F
14	1		*FRONT WIPER PANEL	0.00		*165.00 F
15	1		*WASHER TANK	0.00	40	*130.00 F
16	1		*SPARE TANK	0.00		*25.00 F

F=Franchise part.

Sub Total (\$\$)	1,396.00
+ Margin on L,N Items 10.00% (\$\$)	139.60
Total Parts (\$\$)	1,535.60

Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	40.00
Sub Total (\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	450.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	580.00
Gross Labour Cost (\$)			1,080.00

Kan Fook Sing Motor Workshop/GBJ1728B/21/06/2022 18:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thruon

82235769

24/6/22 1400

OP: EXCESS TBC

not authorized

P/P 4/5 1 day swp