



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Chua Hua Tong BLK 65 NEW UPPER CHANGI RD #09-1136 SINGAPORE 460065 Contact No Mobile: 91868777	Cust No/Name /Chua Hua Tong Reg No/Reg Date SLP3510Z / 01/06/201 Date In/Mileage / 98885 Chassis No KNACC81CVH5079489 Engine No G4LEHS212577 Make/Model KIA/NIRO 1.6 A Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	20/06/2022/ 15:21	TLE	261 / Edwin Caina	53008
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FR BUMPER & LHF FENDER 640 x 2			1289	1289 1920.00
E PNT98000	RESpray FR BUMPER & LHF FENDER 2 x 550			1100	1100 1650.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM			20	20 80.00
M SUNDRY	sundries				50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM			40	40 280.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				120.00
M COVER-FR BUMPER UPR	1.00	632.00	00.00		632.00
M COVER ASSY-FR BUMPER LWR	1.00	346.00	00.00		346.00
M LOGO ASSY-KIA SUB	1.00	61.00	00.00		61.00
M STRIP ASSY-FR BUMPER UPR	1.00	38.00	00.00		38.00
M GRILLE ASSY-RADIATOR	1.00	441.00	00.00		441.00
M PIECE-FRT BUMPER GUARD LWR,LH	1.00	16.00	00.00		16.00
M PIECE-FRT BUMPER GUARD LWR,RH	1.00	16.00	00.00		16.00
M DUCT ASSY-AIR CURTAIN,LH	1.00	32.00	00.00		32.00
M AIR DUCT-FR BUMPER,LH	1.00	39.00	00.00		39.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	68.00	00.00		68.00
M GRILLE-FRONT BUMPER	1.00	232.00	00.00		232.00
M BRACKET-FR BUMPER SIDE,LH	1.00	12.00	00.00		12.00
M LAMP ASSY-FRONT FOG & DRL,LH	1.00	638.00	00.00		638.00
M PANEL-FENDER,LH	1.00	435.00	00.00		435.00
M GUARD ASSY-FRONT WHEEL,LH	1.00	126.00	00.00		126.00
M GARNISH ASSY-FRNDR SIDE,LH	1.00	123.00	00.00		123.00
M LAMP ASSY-HEAD,LH	1.00	937.00	00.00		937.00

Confirm & accepted by

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

7% GST on

Nett

8292.00

Total Payable

8,292.00

580.44

8,872.44

Authorized signatory and company stamp

*Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 *Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.