

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 22.06.2022

Accident Date : 04.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Hyundai Elantra" Reg. No. SKV7990A Claiming Against Your Insured Veh. No. FBR2246B		
1pc	Rear Bumper	3.50	602.00 X
14pcs	Rear Bumper Clips		49.00 X
1pc	Rear Bumper Lower Spoiler		255.00 ✓
1pc	Boot Emblem		36.00 ✓
1pc	Boot Badge Elantra		64.00 ✓
1pc	Boot Badge GLS		33.40 ✓
1pc	Boot Lamp LH		210.00 X
1pc	Taillamp LH		473.00 X
1pc	Taillamp Gasket LH		35.00 X
			1,757.40
			351.48
	Less 20%		1,405.92
1pc	Rear Bumper Reverse Sensor		180.00 SN X
	To Conduct Rear Electrical Check, Locking System, Adjust, Tail Lamp etc		40.00 101
	Labour Charge - Panel Beating, Repairing of Boot, End Panel & Part Replacement		550.00 180
	To Spray Paint Affected Areas		580.00 400
		Total :	2,755.92

*NOT Authorized
Running After Rain*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 days

8900.72

To Conduct Electrical Check
To Dismantle / Transfer Door Fittings / Ancillary Accessories
To Supply End Panel Body Sealant
To Conduct

3.50

85.00
45.00 X
1,128.60 X
49.00 X
9,077.60
1,815.52
7,262.08