



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22005959/Vqy3e2 Date: 06/09/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4660H	Veh. Inspected	GBL 1775D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/22/2032	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	22/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GDH2012017078	Colour	SILVER
	Odometer	29703 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	195/80 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	195/80 R15	BRIDGESTONE	5 mm
	L/H Rear Tyre	195/80 R15	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/06/2022	Inspection Date	22/06/2022
	Survey held at	10 KAKI BUKIT ROAD 2 #03-18 FIRST EAST CENTRE		
	Repairer	THE MECHANIC PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	