



# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133  
 T 65 6758 2222 F 65 6257 6931  
 E sales@scauto.com.sg  
 scauto.com.sg

Co. Reg. No. 199800107D

M/S SOMPO INSURANCE SINGAPORE PTE LTD  
 CITYLINE TRAVEL PTE LTD  
 38 ANG MO KIO INDUSTRIAL PARK 2 #04-09  
 SINGAPORE 569511  
 Insured CITYLINE TRAVEL PTE LTD  
 Policy GA587993

## ESTIMATE BILL

GST Reg. No:  
 Date: 4/7/2022  
 Our Case Ref. SC22/07/085/4CT-TP  
 Accident Date 17/6/2022

Damaged Vehicle No: PA928D

S/no	Description	QTY	Price	Amount	Remark
<b>Replaced Parts</b>					
1	FRONT WINDSCREEN	1 PC	\$ 4,989.90	\$ 4,989.90	✓
2	SEALANT FRAME, WINDSCREEN	1 PC	\$ 586.30	\$ 586.30	✓
3	SEALANT	8 PC	\$ 392.00	\$ 392.00	✓
4	IU BRACKET	1 PC	\$ 20.00	\$ 20.00	✓
5	FRONT ELECTRIC MIRROR LH ASSEMBLY	1 PC	\$ 1,980.90	\$ 1,980.90	✓
6	RECORDING CAMERA LH	1 PC	TBC	TBC	X
5	SUNDRIES	2 PC	\$ 200.00	\$ 200.00	X
<b>Labour Charges</b>					
1	LABOUR TO REMOVE, REINSTALL AND CHECK WIRENESS.			\$ 650.00	32d
2	LABOUR TO REMOVE AND REINSTALL FRONT WINDSCREEN.			\$ 800.00	70d
3	LABOUR TO REMOVE, REPAIR AND REINSTALL FRT ELECTRIC MIRROR LH ASSEMBLY.			\$ 800.00	64d
4	LABOUR TO RESPRAY FRT ELECTRIC MIRROR LH ASSY			\$ 800.00	50d
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK			\$ 250.00	8d
TOTAL				\$11,469.10	

*Not available  
 11 Aug @ 6600h  
 Presurvey After Part  
 Kenneth  
 96910663  
 3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: