



# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133  
T 65 6758 2222 F 65 6257 6931  
E sales@scauto.com.sg  
scauto.com.sg

Co. Reg. No. 199800107D

<b>M/S</b>	CITYLINE TRAVEL PTE LTD
	38 ANG MO KIO INDUSTRIAL PARK 2 #04-09 SINGAPORE 569511
<b>Insured</b>	CITYLINE TRAVEL PTE LTD
<b>Policy</b>	P1918643

## *Final Bill*

GST Reg. No: 19-9800107D  
Date: 26/7/2022  
Our Case Ref. SC22/07/085/4CT-TP  
Accident Date 17/6/2022

**Damaged Vehicle No: PA928D**

S/no	Description	QTY	Price	Disc	Amount
<b><u>Replaced Parts</u></b>					
1	FRONT WINDSCREEN	1 PC	\$4,989.90	-	\$4,989.90
2	SEALANT FRAME, WINDSCREEN	1 PC	\$586.30	-	\$586.30
3	SEALANT	1 PC	\$392.00	-	\$392.00
4	IU BRACKET	1 PC	\$20.00	-	\$20.00
5	SUNDRIES	1 PC	\$50.00	-	\$50.00
<b><u>Labour Charges</u></b>					
1	LABOUR TO REMOVE, REINSTALL AND CHECK WIRENESS.	1	\$320.00	-	\$320.00
2	LABOUR TO REMOVE AND REINSTALL FRONT WINDSCREEN	1	\$700.00	-	\$700.00
3	LABOUR TO REMOVE, REPAIR AND REINSTALL FRT ELECTRIC MIRROR LH ASSEMBLY.	1	\$640.00	-	\$640.00
4	LABOUR TO RESPRAY FRT ELECTRIC MIRROR LH ASSY	1	\$500.00	-	\$500.00
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	\$80.00	-	\$80.00
<b>Sub Total</b>					<b>\$ 8,278.20</b>
<b>Lump Sum</b>					<b>\$ 6,622.56</b>
<b>GST ( 7%)</b>					<b>\$ 463.58</b>
<b>Total Amount</b>					<b>\$ 7,086.14</b>

\_\_\_\_\_  
Authorised Signature