

PROMPT MOTORS PTE.LTD.

BLK 8 KAKI BUKIT AVENUE 4 #02-16

PREMIER @ KAKI BUKIT

SINGAPORE 415875

UEN: 202214492N

Vehicle number: SLK6859A

Make & Model: Honda Odyssey

Chassis number: JHMRC1890GC207574

No.	Description of spare parts	Qty	Amount SS	
1	Tailgate	1	S 1,098.60	DT
2	Tailgate windscreen glass rubber moulding	1set	S 113.80	huc
3	Tailgate centre emblem	1	S 27.80	huc
4	Tailgate RH lamp assy	1	S 405.60	XSC - cr
5	Tailgate LH lamp assy	1	S 405.60	cr
6	Tailgate centre "Odyssey"	1	S 168.70	huc
7	Tailgate number plate lower chrome moulding	1	S 180.10	DL5
8	Tailgate number plate garnish	1	S 165.70	XSC
9	Tailgate lock	1	S 190.30	jab
10	Tailgate lock catch	1	S 28.50	Xr
11	Tailgate inner trim board	1	S 211.70	car
12	Tailgate inner trim board clips	1set	S 60.00	3011C
13	Tailgate inner pull handle	1	S 10.70	XSC
14	Tailgate weatherstrip	1	S 120.60	cut
15	Tailgate switch opener	1	S 108.00	XSC
16	Tailgate RH hinge	1	S 73.20	XSC
17	Tailgate LH hinge	1	S 73.20	XSC
18	Tailgate RH absorber stay	1	S 168.80	XSC
19	Tailgate LH absorber stay	1	S 168.80	XSC
20	Tailgate reverse camera	1	S 734.60	XSC
21	Rear bumper	1	S 557.90	cut
22	Rear bumper RH lower spoiler	1	S 101.20	XSC
23	Rear bumper LH lower spoiler	1	S 101.20	XSC
24	Rear bumper clips	1set	S 70.00	3011C
25	Rear bumper RH upper cover	1	S 78.90	XSC
26	Rear bumper RH upper cover clips	1set	S 30.00	2011C
27	Rear bumper LH upper cover	1	S 78.90	XSC
28	Rear bumper LH upper cover clips	1set	S 30.00	2011C
29	Rear bumper RH reflector	1	S 46.50	cr
30	Rear bumper LH reflector	1	S 46.50	cr
31	Rear bumper RH side retainer	1	S 22.30	huc
32	Rear bumper LH side retainer	1	S 22.30	huc

33	Rear bumper RH side reverse sensor	1	\$	267.80	} total
34	Rear bumper RH centre reverse sensor	1	\$	267.80	
35	Rear bumper LH centre reverse sensor	1	\$	267.80	
36	Rear bumper LH side reverse sensor	1	\$	267.80	
37	Rear bumper reverse sensor retainer lock	4	\$	167.20	X NW
38	RH taillamp assy	1	\$	859.80	X SL
39	LH taillamp assy	1	\$	859.80	X SL
40	End panel	1	\$	472.80	X SL
41	End panel inner garnish	1	\$	106.30	X SL
42	End panel inner garnish clips	1 set	\$	50.00	X SL
43	End panel inner garnish centre cover	1	\$	63.00	X SL
44	Rear buzzer sensor	1	\$	67.70	X SL
45	Rear smart antenna sensor	1	\$	63.40	X SL
46	Rear RH radar sensor	1	\$	1,123.60	X NW
47	Rear RH radar sensor bracket	1	\$	46.80	X NW
48	Rear LH radar sensor	1	\$	1,123.60	X NW
49	Rear LH radar sensor bracket	1	\$	46.80	X NW
50	Rear compartment panel	1	\$	356.80	X SL
51	Rear compartment panel insulator	1	\$	40.70	X SL
52	Rear compartment panel top cover board	1	\$	378.10	X SL
53	Rear RH fender	1	\$	893.80	X SL
54	Rear RH fender inner trim	1	\$	756.60	X SL
55	Rear RH fender inner trim clips	1 set	\$	60.00	X SL
56	Rear RH fender inner aircon blower	1	\$	828.60	X SL
57	Rear RH fender glass rubber moulding	1	\$	19.80	X NW
58	Rear LH fender	1	\$	893.80	X SL
59	Rear LH fender inner trim	1	\$	756.60	X SL
60	Rear LH fender inner trim clips	1 set	\$	60.00	X SL
61	Rear LH fender glass rubber moulding	1	\$	19.80	X NW
62	Exhaust silencer	1	\$	692.80	X SL
63	Exhaust silencer gasket	1	\$	45.00	X SL
			\$	17,624.40	
			Parts less 20%	\$	3,524.88
			Total	\$	14,099.52

No.	Special Nett Items		Amount S\$
1	Tailgate windscreen glass sealant	1	\$ 70.00
2	Tailgate windscreen glass inner seal	1	\$ 50.00
3	Tailgate seal	1	\$ 70.00
4	Rear RH fender joint sealant	1	\$ 75.00

5	Rear RH fender glass sealant	1	\$	60.00	* NW
6	Rear RH fender glass inner seal	1	\$	35.00	* NW
7	Rear LH fender joint sealant	1	\$	75.00	* NW
8	Rear LH fender glass sealant	1	\$	60.00	* NW
9	Rear LH fender glass inner seal	1	\$	35.00	* NW
10	Rear compartment panel joint sealant	1	\$	80.00	* NW
11	Rear number plate	1	\$	70.00	* NW
			Total:	\$	680.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,200.00	700
2	Spray painting on affected areas and panels	\$ 1,800.00	600
3	Check wiring and lighting system on affected areas	\$ 100.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 120.00	30
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 250.00	120
6	Remove and replace tailgate reverse camera to assist repair	\$ 180.00	30
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 120.00	30
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 320.00	100
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 150.00	* NW
10	Remove and reinstall rear RH fender glass to assist repair	\$ 150.00	* NW
11	Remove and reinstall rear LH fender glass to assist repair	\$ 150.00	* NW
12	Remove and replace aircon blower and pipes to assist repair. Refill aircon gas	\$ 450.00	* NW
13	Remove and reinstall roof lining, seats, carpet and seat belts to assist repair	\$ 320.00	* NW
14	Reset and calibration radar unit and fault code after repair	\$ 280.00	* NW

	Total:	\$ 6,590.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 14,099.52

Special Nett: \$ 680.00

Labour: \$ 6,590.00

Total Amount: \$ 21,369.52

Thiruvananthapuram

82235764

22/6/22 | 700

L/S 5 days w/p

F: 64600

pp. 5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: