

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0521/2022/JT
DATE : 23-Jun-22
WIP : 29732

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/6/22

YOUR INSURED VEH NO : SHC 5000 G

STRIKES AUTOMOTIVE SERVICES Pte Ltd

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Attn : Motor Claims Dept

Tel: 6866 2615 - Fax: 6368 7421

Hi Taufikh,

6 days - ok - Jy - 8 Sep 22

OWNER'S NAME : MR KHAW HONG LAN
ADDRESS : BLK 863 TAMPINES ST 83
#08-478
SINGAPORE 520863
TELEPHONE : HP +65 96411042
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100280372-10
VEHICLE NO : **SKD 3720 J**
MODEL CODE : AUDI A4 1.8 TFSI MU
MODEL YEAR : 24/11/2011
ENGINE NO : CDM148510
CHASSIS NO : WAUZZZ8K9CA059440
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Jun-22
PLACE OF ACCIDENT : TAMPINES AVE 10

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKD 3720 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$ 280.00
3	TO DISLDOGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,500.00	\$ 1,750.00
5	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	3,500.00	\$ 2,200.00
6	TO REMOVE AND RENEW REAR AND CENTER EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$	480.00	\$ 480.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	10,632.00	\$ 5,182.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 3720 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,830.00	\$	1,830.00
2	REAR BUMPER FIXING PARTS	1	\$ 238.00		
3	REAR BUMPER INFORCEMENT BEAM	1	\$ 726.00	\$	725.50
4	REAR BUMPER BRACKET HOLDER - LH / RH	2	\$ 504.00		
5	REAR BUMPER SPOILER	1	\$ 297.00	\$	297.00
6	REAR BUMPER GUIDE SECTION - LH	1	\$ 49.00		
7	REAR BUMPER SECURING STRIP	1	\$ 16.00	\$	15.20
8	REAR BUMPER GUIDE SECTION- LH / RH UPPER	2	\$ 53.00		
9	GUIDE SECTION PIN	2	\$ 12.00		
10	REAR PARKING AID SENSOR	2	\$ 530.00		
11	REAR PARKING AID SENSOR SEAL RING	4	\$ 6.00	\$	6.00
12	REAR BUMPER WIRING SET	1	\$ 572.00		
13	REAR LID	1	\$ 3,115.00	\$	3,115.00
14	REAR LID ATTACHMENT PARTS	1	\$ 78.00		
15	REAR LID FLAP GASKET	1	\$ 229.00		
16	REAR LID LOCK - INNER	1	\$ 212.00		
17	REAR LID LOCK COVER	1	\$ 21.00		
18	REAR LID LOCK STRIKER	1	\$ 56.00		
19	REAR LID LOCK ACTUATOR	1	\$ 200.00		
20	REAR PACKING ADHESIVE	1	\$ 36.00	\$	35.90
SUB TOTAL SPARE PARTS		:	\$ 8,780.00	\$	6,024.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SKD 3720 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	<i>c/f</i>			\$ 6,024.60
21	AUDI EMBLEM	1 \$	144.00	\$ 143.50
22	1.8T EMBLEM	1 \$	104.00	\$ 103.50
23	A4 EMBLEM	1 \$	104.00	\$ 103.50
24	TAIL LIGHT INNER - LH	1 \$	295.00	
25	REAR END PANEL - OUTER	1 \$	330.00	
26	REAR END PANEL - LOWER	1 \$	916.00	
27	REAR END PANEL REINFORCEMENT - INNER	1 \$	560.00	
28	REAR SILENCER - LH	1 \$	1,190.00	\$ 1,190.00
29	DUAL CLIP	1 \$	64.00	
30	REAR SILENCER BRACKET	2 \$	124.00	\$ 61.60
31	REAR SILENCER CENTER	1 \$	1,209.00	\$ 1,209.00
32	REAR SILENCER BRACKET - LH / RH	2 \$	96.00	
33	REAR SILENCER HEAT SHIELD - LH	1 \$	172.00	
34	REAR SILENCER CENTER HEAT SHELF	1 \$	331.00	
35	REAR END PANEL TRIM	1 \$	210.00	
36	LUGGAGE COMPARTMENT FLOOR COVER	1 \$	786.00	
37	REAR NO PLATE	S/N \$	60.00	
38	ARYLIC SEALANT	S/N \$	180.00	
39	CAVITY WAX	S/N \$	140.00	
40	STONE CHIP	S/N \$	180.00	
41	METAL FILLER POWDER	S/N \$	280.00	
42	SUPPLEMENTARY	\$	716.00	\$ 715.00
43	SUNDRIES	\$	400.00	\$ 19.00
TOTAL SPARE PARTS			\$ 17,371.00	\$ 9,569.70
TOTAL LABOUR CHARGES			\$ 10,632.00	\$ 5,182.00
GRAND TOTAL			\$ 28,003.00	\$ 14,751.70

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-12/08/22



Supplementary Estimate

GST Reg No. 19-9902271-W

STRIKES AUTOMOTIVE SERVICES Pte Ltd 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 Attn : Motor Claims Dept Tel: 6866 2615 - Fax: 6368 7421		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0521/2022/JT 8-Jul-22 GLORY 1 of 1 SKD 3720 J AUDI A4 1.8 TFSI MU
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	WHEEL HOUSING LINER REAR - LHS	\$ 241.00	\$ 240.50
2	LHS TAILLIGHT OUTER	\$ 411.00	\$ 410.50
3	CENTER EXHAUST DUAL CLIP	\$ 64.00	\$ 64.00
GRAND TOTAL		\$ 716.00	\$ 715.00

For Premium Automobiles Pte Ltd

 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT