

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKD 37201

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✓	✓
3	TO DISLDOGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	X u u
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	700 \$ 4,500.00	1400. 1750 ✓
5	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$ 3,500.00	1500 2200
6	TO REMOVE AND RENEW REAR AND CENTER EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$ 480.00	77 ✓ ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 10,632.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 37201

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER	1	\$	/ 1,830.00	de 1830
2	REAR BUMPER FIXING PARTS	1	\$	238.00	X un
3	REAR BUMPER INFORCEMENT BEAM	1	\$	/ 726.00	bt 725.50
4	REAR BUMPER BRACKET HOLDER - LH / RH	2	\$	504.00	X un
5	REAR BUMPER SPOILER	1	\$	/ 297.00	de 297
6	REAR BUMPER GUIDE SECTION - LH	1	\$	49.00	X un
7	REAR BUMPER SECURING STRIP	1	\$	/ 16.00	na 15.20
8	REAR BUMPER GUIDE SECTION- LH / RH UPPER	2	\$	53.00	} un
9	GUIDE SECTION PIN	2	\$	12.00	
10	REAR PARKING AID SENSOR	2	\$	530.00	
11	REAR PARKING AID SENSOR SEAL RING	4	\$	/ 6.00	na 6
12	REAR BUMPER WIRING SET	1	\$	572.00	X un
13	REAR LID	1	\$	/ 3,115.00	bt 3115
14	REAR LID ATTACHMENT PARTS	1	\$	78.00	X
15	REAR LID FLAP GASKET	1	\$	229.00	X
16	REAR LID LOCK - INNER	1	\$	212.00	X
17	REAR LID LOCK COVER	1	\$	21.00	X
18	REAR LID LOCK STRIKER	1	\$	56.00	X
19	REAR LID LOCK ACTUATOR	1	\$	200.00	X
20	REAR PACKING ADHESIVE	1	\$	/ 36.00	na 35.90
SUB TOTAL SPARE PARTS		:	\$	8,780.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 37201

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AUDI EMBLEM	1	\$	/ 144.00 net	143.50
22	1.8T EMBLEM	1	\$	/ 104.00 net	103.50
23	A4 EMBLEM	1	\$	/ 104.00 net	103.50
24	TAIL LIGHT INNER - LH	1	\$	295.00 X	
25	REAR END PANEL - OUTER	1	\$	330.00 ?	
26	REAR END PANEL - LOWER	1	\$	916.00 ? photo	
27	REAR END PANEL REINFORCEMENT - INNER	1	\$	560.00 ?	
28	REAR SILENCER - LH	1	\$	/ 1,190.00 ? net	1190
29	DUAL CLIP	1	\$	64.00 ? net	
30	REAR SILENCER BRACKET	2	\$	/ 124.00 ? net	61.60
31	REAR SILENCER CENTER	1	\$	/ 1,209.00 ? net	1209
32	REAR SILENCER BRACKET - LH / RH	2	\$	96.00 ?	
33	REAR SILENCER HEAT SHIELD - LH	1	\$	172.00 ?	
34	REAR SILENCER CENTER HEAT SHELF	1	\$	331.00 ?	
35	REAR END PANEL TRIM	1	\$	210.00 ?	
36	LUGGAGE COMPARTMENT FLOOR COVER	1	\$	786.00 ?	
37	REAR NO PLATE	S/N	\$	60.00 X	
38	ARYLIC SEALANT	S/N	\$	180.00 ?	
39	CAVITY WAX	S/N	\$	140.00 ?	
40	STONE CHIP	S/N	\$	180.00 ?	
41	METAL FILLER POWDER	S/N	\$	280.00 ?	
42	SUNDRIES		\$	/ 400.00 ? 19 net	
TOTAL SPARE PARTS			:	\$	16,655.00
TOTAL LABOUR CHARGES			:	\$	10,632.00
GRAND TOTAL			:	\$	27,287.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

STRIKES AUTOMOTIVE SERVICES Pte Ltd
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705
Attn : Motor Claims Dept

Tel: 6866 2615 - Fax: 6368 7421

Estimate No. PA/TP/0521/2022/JT
Date 8-Jul-22
Service Advisor GLORY
Pages 1 of 1
Regn No SKD 3720 J
Model No AUDI A4 1.8 TFSI MU

Quantity	Description	Unit Price	Amount
Labours			
1	WHEEL HOUSING LINER REAR - LHS torn	\$ 241.00	\$ 240.50
2	LHS TAILLIGHT OUTER cracked	\$ 411.00	\$ 410.50
3	CENTER EXHAUST DUAL CLIP distorted	\$ 64.00	\$ 64.00
GRAND TOTAL		\$ 716.00	\$ 715.00

For Premium Automobiles Pte Ltd

COVER LAB MAT MAT 2 SUPP 1 SURVEYOR'S PARTICULARS

Ready

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

Tanfuk 97495749/62563561
 WP' 24/6/22 E 1040
 Resurvey before paint

PLEASE NOTE :

66 days
 tanfuk@phoenix.com
 THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT