

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST072/22/CIS

Your Ref: To be advised

20-Jun-22

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Toyota Dyna no: GBJ1862X

Date of accident: 14-06-22

Parts supply:

1 pc Front panel *Dented*
1 pc Front panel emblem - DYNA *Neu*
1 pc Front grille *Neu*
1 pc Front grille emblem *Neu*
2 pcs Headlamp @\$748.95 *RH 2 dented*
1 pc Front bumper *Dented*
2 pcs Front bumper brackets @\$98.50 *new*
1 pc Front windscreen rubber *Neu*

S\$ 1,195.90 ✓
65.90 ✓
596.90 X
70.55 X
748.95 + 497.90 = 1246.85 ✓
690 - 748.95 = -58.95 ✓
197.00 +
215.90 ✓
4,589.00

Less 25%: (1,147.25)

S/Nett Items

1 pc Front panel top sticker - Certis CISCO (S/Nett)
1 pc Front panel top sticker - AUXILIARY POLICE (S/Nett)
2 pcs Headlamp wiremesh @\$120.00 (S/Nett) *new*
1 pc Front no. plate (S/Nett) *new*

100.00 80
100.00 80
240.00 +
30.00 +

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To remove and refit dashboard

To remove and refit front windscreen

To remove and refit aircon and top up aircon gas

To check wiring

1350 900.00 600
800.00 600
350.00 +
120.00 ✓
120.00 +
250.00 30
6,451.75

Adrian Lj

H/s 20/06/22

OS Amp

total: 3697.98

H/s: 2950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: