



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6099M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	PANEL-DOOR FRT RH (SN)	DENTED	2,449.60	2,204.64
1	PANEL-DOOR REAR RH (SN)	DENTED	2,537.00	2,283.30
1	FINISHER CHROME UPPE (SN)	NECESSARY	216.00	194.40
1	FINISHER CHROME LOWE (SN)	NECESSARY	204.10	183.69
1	MOULDING-FRT RH DOOR (SN)	NECESSARY	134.10	120.69
1	FINISHER CHROME UPPE (SN)	NECESSARY	150.10	135.09
1	FINISHER CHROME LOWE (SN)	NECESSARY	188.10	169.29
1	FINISHER DOOR REAR C (SN)	NECESSARY	120.40	108.36
1	SEAL-DOOR FRT (SN)	NECESSARY	318.00	286.20
1	SEAL-DOOR RR (SN)	NECESSARY	259.70	233.73
1	FINISHER DOOR REAR B (SN)	NECESSARY	144.10	129.69
1	HANDLE-DOOR FRT (SN)	CUT	472.00	424.80
1	BEZEL HANDLE FRT (SN)	CUT	67.90	61.11
1	HANDLE-DOOR RR (SN)	CUT	472.00	424.80
1	BEZEL HANDLE RR (SN)	CUT	67.90	61.11
2	NOISE DEADENING PAD @\$606.90 (SN)	NECESSARY	1,213.80	1,092.42
1	SEAM SEALANT (SN)	NECESSARY	49.00	44.10
			9,063.80	8,157.42
	<b><u>LABOUR</u></b>			
	TO REPLACE FRT DOOR RH, FRT SE FINISHER, MLDG CHROME, FRT OUTER HANDLE RH, RR DOOR RH, RR SEAL, FINISHER, MLDG CHROME, RR OUTER HANDLE RH, ETC REPAIR RR QTR PANEL RH.		4,300.00	3,250.00
	TO SPRAY FRT DOOR RH, FRT OUTE HANDLE RH, RR DOOR RH, RR OUTER HANDLE RH, RR QTR PANEL RH, ETC.		4,000.00	3,500.00
	TO REMOVE & TRANSFER FRT DOOR INTERIOR COMPONENTS.		500.00	500.00
	TO REMOVE & TRANSFER RR DOOR R INTERIOR CMONENTS.		500.00	500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
			9,921.00	8,371.00
<b>GRAND TOTAL</b>			<b>18,984.80</b>	<b>16,528.42</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>16,528.42</b>

Report Ref No. CS/SMR22005965/Evy3m4

**CHEN TSUE YEE**

Automotive Assessor

**ANG BRYAN TANI**

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.