



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300882

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/02/2023
Reference CC3/CTI22005967/Rpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3631T
Insured Veh. YP 8134P
Claim No. SNM22D204426/C02
Policy No. DMCVSNA00038052201
Accident Date 16/06/2022
Inspection Date 20/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22005967/Rpa3q2 Date: 15/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 8134P	Veh. Inspected	SHD 3631T
	Policy No.	DMCVSNA00038052201	Coverage (\$)	0.00
	Claim No.	SNM22D204426/C02	Excess (\$)	0.00
	Assign From		Assign Date	20/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I40 1.7 CRDI	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMGU093678	Colour	BLUE
	Odometer	570074 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/06/2022	Inspection Date	20/06/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3631T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH / RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	SCRATCHED	228.00	228.00
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,935.40	-
	LESS 20% DISCOUNT		-758.20	-271.20
			3,032.80	1,084.80
	<u>SPECIAL NETT ITEMS</u>			
1	BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			230.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	40.00
	REMOVE / REFIX REAR EXHAUST.	NOT NECESSARY	60.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			1,040.00	570.00
	GRAND TOTAL		4,302.80	1,704.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CC3/CTI22005967/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3631T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3631T

RE-INSPECTION

