

China (H/S)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.06.2022

Time: 08:45:10

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305520160
REGN NO : SHB2196A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 06.10.2016
DATE/TIME IN : 18.06.2022 00:15
ACCIDENT DATE : 18.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER# <i>le</i>	1	553.00	20.00	442.40	✓
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR <i>rec</i>	10	22.00	20.00	17.60	✓
0003	04-01-0103-1150-A	PROTECTOR MAT <i>rec</i>	1 N	50.00	2.00-	50.00	✓
0004	04-01-0103-0574-A	PANEL-FENDER LH+ <i>buc</i>	1	2,171.40	20.00	1,737.12	✓
0005	04-01-0103-0658-G	CAP ASSY-WHEEL HUB <i>ca</i>	1	214.20	20.00	171.36	✓
0006	03-01-0103-0098-G	WHEEL ASSY-STEEL <i>7Xm</i>	1	650.30	20.00	520.24	
0007	03-01-0103-0112-G	ARM + BUSH ASSY-SUSP UPR <i>7bf</i>	1	355.75	20.00	284.60	✓
0008	03-01-0103-0114-G	ARM COMPLETE-RR LWR RH <i>7Xm</i>	1	353.80	20.00	283.04	
0009	03-01-0103-0116-G	ARM ASSY- RR TRAILING ARM <i>7bf</i>	1	384.00	20.00	307.20	✓
0010	03-01-0103-0118-G	SHOCK ABSORBER ASSY-RR <i>7Xm</i>	1	341.85	20.00	273.48	
0011	03-01-0103-0127-G	COVER-RR SHOCK ABSORBER <i>7Xm</i>	1	81.30	20.00	65.04	
0012	03-01-0103-0125-G	BAR ASSY-FR STABILIZER <i>7Xm</i>	1	199.60	20.00	159.68	
0013	05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC <i>rec</i>	2 N	46.00	2.00-	46.00	✓

3056.28

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 20.06.2022
Time: 08:45:10
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305520160
REGN NO : SHB2196A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 06.10.2016
DATE/TIME IN : 18.06.2022 00:1
ACCIDENT DATE : 18.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 4,357.76

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 17-01	CHECK ALL LIGHTING
0003 20-00	TUFF COAT ON AFFECTED PARTS.
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR
0005 L	REMOVE/REFIX REVERSE SENSOR
0006 L	REMOVE/REFIX REAR WINDSCREEN
0007 20-12	REMOVE/REFIX REAR SUSPENSION
0008 20-08	ADJUST FRONT WHEEL ALIGNMENT

1200.00	840
600.00	500
520.00	30
530.00	40
120.00	60
50.00	40
120.00	
120.00	100 ³
100.00	60

1790

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305520160
 REGN NO : SHB2196A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 06.10.2016
 DATE/TIME IN : 18.06.2022 00:1
 ACCIDENT DATE : 18.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0009 23-01

TOWING FEE

~~reco~~

60.00

SUB-TOTAL : 3,420.00

TOTAL : 7,777.76

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revised
 Hq 900 100 68

6 days
 4/5

20/06/22 @ 1610

Resy after repair

3056.28
 1790.00
 60.00
 1850.32
 6756.60
 20%
 5405.28

4/5 - \$5,400

[illegible]