

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 24 Jun 2022

Preliminary Advice

Vehicle No	: SLR3717J	Accident Date	: 17/06/2022
Make	: MITSUBISHI SPACE STAR	Policy No.	: MPC21B00019900
Assignment Date	: 22/06/2022	Excess	: S\$0.00
Date of Inspection	: 23/06/2022	Est. Duration of Repair	: 4
Inspection At	: RICARDO AUTO CENTRE PTE LTD (HQ) 160 SIN MING DRIVE, #02-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,929.70
Revised Amount	:S\$	3,169.70
Check Items (Estimated)	:S\$	363.00
Total	:S\$	3,532.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	17,621.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 32,379.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.