

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 June 2022 4:46 PM
To: Grace
Cc: SUR
Subject: ECICS-OD SLR 3717J DOA: 17/06/2022

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLR 3717J at repair cost not more than \$2,500.00 on Lump Sum basis or whichever lower (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)