

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21B00019900	Date of Loss:	17/06/2022
Vehicle Reg. No.:	SLR3717J	Driveable?	
Driver Age/Info:	35 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE MAY LING	Contact No:	+6597686353
Driver:	LEE MAY LING		
Make/Model:	MITSUBISHI SPACE STAR, 1.2 CVT (A)	Vehicle Reg. Date:	14/08/2017
Vehicle Colour:	Green		
Engine No:	3A92UGD8138	Chassis No:	MMCXTA03AGH049754
Odometer:	20032 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	RICARDO AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS		Amount
Parts		3,329.70
Miscellaneous Items		0.00
Labour		1,600.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		4,929.70
+ GST 7.00% (S\$)		345.08
Nett Amount (S\$)		5,274.78

This claim is handled by: **GRACE TAN KIAN ANN**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2022)
 Parts: 144 MITSUBISHI SPACE STAR 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH FRONT FENDER <i>bt</i>	0.00	0.00	*230.00 F ✓
2	1		*LH FRONT FENDER SHIELD <i>? x nn</i>	0.00	0.00	*65.00 F
3	10		*LH FRONT FENDER SHIELD CLIPS <i>nn</i>	0.00	0.00	*30.00 F ✓
4	1		*BONNET INSULATOR <i>x nn</i>	0.00	0.00	*90.00 F
5	10		*BONNET INSULATOR CLIPS <i>x nn</i>	0.00	0.00	*30.00 F
6	1		*HEAD LAMP - LH <i>nn</i>	0.00	0.00	*1,200.00 F ✓
7	1		*FRONT BUMPER <i>nn</i>	0.00	0.00 <i>40%</i>	*450.00 F ✓
8	1		*FRONT BUMPER REINFORCEMENT <i>? x nn</i>	0.00	0.00	*210.00 F
9	10		*FRONT BUMPER CLIPS <i>nn</i>	0.00	0.00	*35.00 F ✓
10	1		*FRONT BUMPER SIDE RETAINER LH <i>nn</i>	0.00	0.00	*10.00 F ✓
11	1		*FRONT BUMPER FOG LAMP LH <i>nn</i> (FOG LAMP COVER)	0.00	0.00	*38.00 F ✓
12	1		*FRONT BUMPER FOG LAMP GARNISH SIDE LH <i>nn</i>	0.00	0.00	*68.00 F ✓
13	1		*HEAD LAMP SUPPORT LH <i>? x nn</i>	0.00	0.00	*55.00 F
14	1		*FRONT SUPPORT PANEL <i>x nn</i>	0.00	0.00	*450.00 F
15	1		*FENDER EMBLEM <i>nn</i>	0.00	0.00	*38.00 F
16	1		*FENDER CHROME GARNISH <i>nn</i>	0.00	0.00	*28.00 F ✓

F=Franchise part.

Sub Total (S\$) *2039* 3,027.00
 + Margin on L,N Items 10.00% (S\$) *+ 10% = 2242.90* 302.70

Total Parts (S\$) 3,329.70

Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO FOCUS HEADLAMP	New	30.00 ✓
2	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	New	650.00 400
3	TO SERVICE AIRCON SYSTEM, VACUUM & TOP UP GAS.	New	120.00 X
4	TO SPRAY PAINT ON REPAIRED AREAS	New	800.00 400
Gross Labour Cost (S\$)			1,600.00

Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rare
Hp 90010068
4 days
45 P/P
23/06/22
@1415
EXCESS: TBA
Rare
Resurvey after repair

12/12/22, 12:14 PM

Estimate Report

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	SUPPLY WEEK END CAR PLATE <i>✓</i>	45.00
2	1	WEEK END CAR BREAK SEAL & LOCK SEAL ENABLE TO REMOVE & REPLACE FRONT BUMPER <i>✓</i>	60.00

Sub Total (S\$) 105.00

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2242.90

830.00

105.00

3177.90

4 days