

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0508/2022/JT
DATE : 20-Jun-22
WIP : 29276

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

9-Sep-22

OWNER'S NAME : MR TIONG YANG WEI, DAVID
ADDRESS : 85 COMPASSVALE BOW
#06-19
SINGAPORE 544685
TELEPHONE : HP +65 97427290
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070007814-01
VEHICLE NO : **SGG 5330 U**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 21/1/2020
ENGINE NO : CZD 885227
CHASSIS NO : WAUZZZF32L1024380
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jun-22
PLACE OF ACCIDENT : ROBINSON ROAD JUNCTION OF
BEFORE CROSS ST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGG 5330 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,972.00	\$ 2,272.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGG 5330 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,073.00	
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00	
3	FRONT BUMPER GRILLE - RH	1	\$ 124.00	
4	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
5	FRONT BUMPER SPOILER	1	\$ 426.00	\$ 340.80
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	
8	FRONT FENDER - RH	1	\$ 1,445.00	
9	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
10	FRONT FENDER BRACE - RH	1	\$ 98.00	
11	FRONT FENDER BRACKET - RH	1	\$ 39.00	
12	FRONT WHEEL HOUSING LINER	1	\$ 260.00	
13	FRONT WHEEL HOUSING LINER COVER - RH	1	\$ 18.00	
14	FRONT WHEEL COVER - LH / RH	2	\$ 566.00	\$ 452.00
15	HEADLIGHT MOUNTING - RH	1	\$ 132.00	
16	HEADLIGHT - RH	1	\$ 5,952.00	
17	LIFT CYLINDER - RH	1	\$ 231.00	
18	LIFT CYLINDER HOSE	1	\$ 92.00	
19	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 11,364.00	\$ 792.80
TOTAL LABOUR CHARGES			\$ 5,972.00	\$ 2,272.00
GRAND TOTAL			\$ 17,336.00	\$ 3,064.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-=18/08/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT