



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0502/2022/JT
DATE : 17-Jun-22
WIP : 29100

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. GOH SOON YONG
ADDRESS : BLK 856E TAMPINES ST 82
#04-198
SINGAPORE 525856
TELEPHONE : HP +65 96207800
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900230537-02
VEHICLE NO : **SMQ 1090 P**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 30/10/2019
ENGINE NO : CZD 886363
CHASSIS NO : WAUZZZF38L1011911
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jun-22
PLACE OF ACCIDENT : TURNING SIDE LANE FROM SCOTT
ROAD TO ORCHARD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 1090 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$ 2,000.00	1100
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,152.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1090 P

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Defect</i>	1	\$ 1,738.00	✓
2	REAR BUMPER FIXING PARTS <i>Not in</i>	1	\$ 220.00	✗
3	REAR BUMPER SPOILER <i>Not Nec</i>	1	\$ 510.00	✗
4	REAR BUMPER REINFORCEMENT - CENTER <i>Not in</i>	1	\$ 108.00	✗
5	REAR BUMPER BRACKET <i>Not in</i>	1	\$ 53.00	✗
6	REAR LIGHT REFLECTOR - RH <i>Cracked</i>	1	\$ 46.00	✓
7	TAIL LIGHT - RH OUTER <i>Cracked</i>	1	\$ 1,030.00	✗
8	TAIL LIGHT TRIM OUTER - RH <i>Cracked</i>	1	\$ 34.00	✗
9	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 71.00	✗
10	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 566.00	✓
11	SUNDRIES <i>?</i>		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 4,676.00	
TOTAL LABOUR CHARGES		:	\$ 4,152.00	
GRAND TOTAL		:	\$ 8,828.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King -*
SURVEYED DATE : *22/06/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT