* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA,KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/OD/0502/2022/JT

DATE : 17-Jun-22 WIP : 29100

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120 Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. GOH SOON YONG

ADDRESS : BLK 856E TAMPINES ST 82

#04-198

SINGAPORE 525856

 TELEPHONE
 : HP +65 96207800

 TYPE OF CLAIM
 : OWN DAMAGE CLAIM

 POLICY NO
 : 1900230537-02

POLICY NO : 1900230537 VEHICLE NO : SMQ 1090 P

MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC

MODEL YEAR : 30/10/2019 ENGINE NO : CZD 886363

CHASSIS NO : WAUZZZZF38L1011911

MILEAGE : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 16-Jun-22

PLACE OF ACCIDENT : TURNING SIDE LANE FROM SCOTT

ROAD TO ORCHARD





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 1090 P

S/N	NATURE OF JOBS			CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$	360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	1,600.00	500
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.		S	2,000.00	1103
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N	\$	192.00	/
	TOTAL LABOUR CHARGES	:	\$	4,152.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1090 P

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER Delad	1	\$ 1,738.00	/
2	REAR BUMPER FIXING PARTS Note A	1	\$ 220.00	t .
3	REAR BUMPER SPOILER NOC NEC	1	\$ 510.00	*.
4	REAR BUMPER REINFORCEMENT - CENTER X	1	\$ 108.00	×.
5	REAR BUMPER BRACKET	1	\$ 53.00	t .
6	REAR LIGHT REFLECTOR - RH Coulied	1	\$ 46.00	
7	TAIL LIGHT - RH OUTER 2	1	\$ 1,030.00	+
8	TAIL LIGHT TRIM OUTER - RH	1	\$ 34.00	+
9	REAR BUMPER GUIDE SECTION - RH	1	\$ 71.00	*
10	REAR WHEEL ARCH COVER - LH / RH	2	\$ 566.00	
11	SUNDRIES .		\$ 300.00	?
	TOTAL SPARE PARTS	:	\$ 4,676.00	
	TOTAL LABOUR CHARGES	:	\$ 4,152.00	
	GRAND TOTAL	:	\$ 8,828.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

:

NAME

SURVEYED DATE AUTHORISED DATE

EXCESS COST

LIABILITY REMARKS

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

Adrian hiny -22/06/220 Xhel Authorised, 04 Pergs.

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT