

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 1090 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Deland</i>	1	\$ 1,738.00	✓
2	REAR BUMPER FIXING PARTS <i>Not on</i>	1	\$ 220.00	+
3	REAR BUMPER SPOILER <i>Not on</i>	1	\$ 510.00	+
4	REAR BUMPER REINFORCEMENT - CENTER <i>Not on</i>	1	\$ 108.00	+
5	REAR BUMPER BRACKET <i>Not on</i>	1	\$ 53.00	+
6	REAR LIGHT REFLECTOR - RH <i>Not on</i>	1	\$ 46.00	✓
7	TAIL LIGHT - RH OUTER <i>Not on</i>	1	\$ 1,030.00	+
8	TAIL LIGHT TRIM OUTER - RH <i>Not on</i>	1	\$ 34.00	+
9	REAR BUMPER GUIDE SECTION - RH <i>Not on</i>	1	\$ 71.00	+
10	REAR WHEEL ARCH COVER - LH / RH <i>Not on</i>	2	\$ 566.00	✓
11	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 4,676.00	
TOTAL LABOUR CHARGES		:	\$ 4,152.00	
GRAND TOTAL		:	\$ 8,828.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Li
H.S.
Resurveyed