

KS AUTOMOBILE
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (737869)
Tel: 93911482

TO	: CHINA TAIPING	DATE	: 22-Jun-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<i>VERON</i>			
<u>VEHICLE DETAILS</u>			
		VEHICLE NO	: SMC2839P
		MODEL	: HONDA CIVIC
THIRD PARTY REQUESTOR / CONTACT :		DAUD/93911482	<i>JAMF0630652103 0</i>

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 868.30	\$ 868.30
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 324.10	\$ 324.10
3	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 398.60	\$ 398.60
4	FRONT BUMPER SIDE RETAINER <i>damaged</i>	2	\$ 62.20	\$ 124.40
5	FRONT BUMPER FOG LAMP LH <i>Cracked</i>	1	\$ 425.20	\$ 425.20
6	FRONT GRILLE EMBLEM <i>new</i>	1	\$ 93.50	\$ 93.50
7	BONNET <i>Buckled</i>	1	\$ 1,022.40	\$ 1,022.40
8	BONNET HINGE <i>new</i>	2	\$ 58.90	\$ 117.80
9	BONNET LOCK <i>new</i>	1	\$ 258.20	\$ 258.20
10	FRONT FENDER LH <i>Distorted</i>	1	\$ 612.00	\$ 612.00
11	FRONT FENDER INNER SHIELD <i>torn LH</i>	2	\$ 119.40	\$ 238.80
12	FRONT SUPPORT PANEL <i>new</i>	1	\$ 785.20	\$ 785.20
13	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 321.20	\$ 321.20
14	HEADLAMP <i>LH unit.</i>	2	\$ 1,024.00	\$ 2,048.00
15	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 124.00	\$ 248.00
16	A/C CONDENSER <i>new</i>	1	\$ 1,542.00	\$ 1,542.00
17	RADIATOR <i>new</i>	1	\$ 1,574.60	\$ 1,574.60
18	RADIATOR RESERVE TANK <i>new</i>	1	\$ 147.30	\$ 147.30
19	RESONATOR CHAMBER <i>new</i>	1	\$ 356.40	\$ 356.40
20	FRONT KNUCKLE ARM LH <i>Damaged</i>	1	\$ 490.50	\$ 490.50

638.

+

+

32

224

+

606

+

+

537.

165

+

+

1924.

912

+

+

+

+

189.

+

✓

21	FRONT KNUCKLE BEARING <i>Replaced</i>	1	\$ 202.80	\$ 202.80	✓
22	FRONT LOWER ARM LH <i>Best</i>	1	\$ 473.90	\$ 473.90	258
23	FRONT STABILIZER LINK LH <i>He m</i>	1	\$ 187.60	\$ 187.60	X
24	FRONT ABSORBER ASSY LH <i>Best</i>	1	\$ 585.70	\$ 585.70	343
25	STEERING TIE ROD <i>He m</i>	1	\$ 127.20	\$ 127.20	X

4597.30
3677.84

TOTAL PRICE \$ 13,573.70
LESS 20% \$ 2,714.74
SUB TOTAL PRICE \$ 10,858.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP SET <i>He m</i>	1	\$ 65.00	\$ 65.00	30.
2	FRONT BUMPER LOWER SPOILER <i>Dehind</i>	1	\$ 1,200.00	\$ 1,200.00	650.
3	FRONT GRILLE <i>He m</i>	1	\$ 800.00	\$ 800.00	X
4	FRONT GRILLE EMBLEM PUSH NUT <i>He m</i>	1	\$ 10.00	\$ 10.00	X.
5	BONNET INSULATOR CLIP SET <i>He m</i>	1	\$ 70.00	\$ 70.00	X.
6	FRONT FENDER INNER SHIELD CLIP SET <i>He m</i>	1	\$ 95.00	\$ 95.00	30.
7	SPORT RIM <i>Cit</i>	1	\$ 1,500.00	\$ 1,500.00	450
8	WHEEL CAP (SET) <i>3 per m</i>	1	\$ 150.00	\$ 150.00	X
9	ENGINE COOLANT	2	\$ 25.00	\$ 50.00	X 1160

SUB TOTAL PRICE \$ 3,940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 1,000.00	600	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,000.00	600	
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	30	
4	REMOVE AND INSTALL FRONT LHS UNDER-CARRIAGE COMPONENT.	\$ 300.00	220	
5	WHEEL ALIGNMENT.	\$ 150.00	80	
6	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	\$ 150.00	X.	

7	PASSENGER AIR-BAG, WIRING HARNESS, SEAT BELTS AND SRS CONTROL UNIT. RESET SRS SYSTEM WITH ON-BOARD DIAGNOSTIC	\$ 200.00	X	
8	DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	\$ 180.00	X	

1530

SUB TOTAL

\$ 3,060.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,798.96
TOTAL LABOUR COST : \$ 3,060.00
TOTAL REPAIR COST : \$ 17,858.96

Adrian Lj
24/06/22
66 Days.

total: 6367.84
L/S: 5.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: