

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	---

Attn: Priya

Date: 21 Jul 2022

Preliminary Advice

Vehicle No	: FBH8825T	Accident Date	: 06/06/2022
Make	: YAMAHA YBR125	Policy No.	: D20MFL0000637-02
Assignment Date	: 23/06/2022	Excess	: S\$0.00
Date of Inspection	: 23/06/2022	Est. Duration of Repair	: 3
Inspection At	: KANG CAR REPAIRERS PTE LTD (HQ) NO 1 KAKI BUKIT AVE 6, #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,309.87	(INCLUSIVE OF SUPPLEMENTARY)
Revised Amount	:S\$	2,137.55	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	2,137.55	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value	:S\$	2,500.00
COE / PARF Rebate	:S\$	222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,278.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.