### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte

Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Priya Date: 24 Jun 2022

# **Preliminary Advice**

Vehicle No : FBH8825T Accident Date : 06/06/2022

Make : YAMAHA YBR125 Policy No.

D20MFL0000637-

02

Assignment

Date

: 23/06/2022

Excess

: S\$0.00

Date of

: 23/06/2022

Est. Duration of

Inspection Repair : 3

Inspection At: KANG CAR REPAIRERS PTE LTD (HQ)

NO 1 KAKI BUKIT AVE 6, #02-06 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 2,255.12 Revised Amount :S\$ 2,071.85 Check Items (Estimated) :S\$ 0.00 :S\$ Total 2,071.85

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 2,500.00 COE / PARF Rebate :S\$ 222.00

Salvage Value :S\$

Margin for Repair :S\$ 2,278.00

### Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.