



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS/III22005988/Kqy3 Date: 23/06/2022 Code: III2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	PC 9606M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	BHUVANESWARI	Assign Date	23/06/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/06/2022	Inspection Date	23/06/2022
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			