


MY CAR CREDIT PTE LTD

*Not Authorized
17
4901-*



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/INDIA
Policy No:	D22MFL0001917	Date of Loss:	17/06/2022
Vehicle Reg. No.:	PC9606M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO MEDCARE PTE LTD		
Driver:	CHNG KAH HOE		

Make/Model:	TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)	Vehicle Reg. Date:	26/03/2021
Vehicle Colour:	WHITE	Chassis No:	JTFST22P300040327
Engine No:	1KDB069053		
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **0**

*Not Authorized
Repair B & paint
Ex TBA
6 days*

Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

83219.50

COST OF CLAIMS	Amount
Parts	1,518.00
Miscellaneous Items	106.00
Labour	1,780.00
Paintwork Labour	0.00
Shipping	0.00
Gross Total (S\$)	3,404.00
+ GST 7.00% (S\$)	238.28
Nett Amount (S\$)	3,642.28

claim is handled by: SHARON CHIONG BENG CHOON

*81012
10/10
10/10*

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Jun 2022)
 Parts: N/A TOYOTA HIACE 3.0 D HIGH ROOF COMMUTER TURBO (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

PC9606M
 OD/India

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	Ry *155.00 F ✓
2	1		*6 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	Ne *12.00 F ✓
3	1		*1 PC TAILGATE	0.00	0.00	Ry *850.00 F ✓
4	1		*1 PC TAILGATE LOGO	0.00	0.00	Ne *38.00 F ✓
5	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	Ry *125.00 F X
6	1		*1 PC TAILGATE STICKER (HIACE)	0.00	0.00	Ne *30.00 F ✓
7	1		*1 PC REAR PANEL OUTER	R 0.00	0.00	Ry *170.00 F X
Sub Total (S\$)						1,380.00
+ Margin on L,N Items 10.00% (S\$)						138.00
Total Parts (S\$)						1,518.00

Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC HANDICAPPED STICKER	Ne 30.00 ✓
2	1	1 PC REAR WINDSCREEN GLASS GUM	Ne 40.00 ✓
3	1	1 PC STICKER - 60KM/H	Ne 10.00 ✓
4	1	1 PC STICKER - ME 106	Ne 15.00 ✓
5	1	OD/TP Case (Insurer)	Ne 11.00 ✓
1 set reverse sensor #280/4N Photo ✓ 2 cases			
Sub Total (S\$)			106.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00 ✓
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER ASSY, LOCK ASSY, TO CUT, WELD & RENEW REAR PANEL OUTER AND REALIGN THE SAME	New	650 800.00
3	PUTTY & RESPRAY ON REAR END PANEL, REAR BUMPER, TAILGATE	New	680 800.00
4	REMOVE & REFIX REVERSE CAMERA, CCTV RECORDER, REVERSE SENSOR AND RESET SYSTEM	New	60 80.00
⑤ Advertisement - #250 ? (Insurer) ✓ Ne			
Gross Labour Cost (S\$)			1,780.00

Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Insurance Consultants have notified the Insurer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: