



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

M2201025-137

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : TOKIO MARINE INSURANCE SINGAPORE
20 MCCALLUM STREET #09-01

Document No. : SQT22000625

Page 1

Date : 2. Mar 2022

Customer No. : WT002

Svc Advisor : SUHELMI

Engine No : L13B11030507

Date | Time : 2. Mar 2022 5:48:25 PM

Surveyor Name :

Survey Date :

Authorisation Date :

SINGAPORE 069046

Registration No : SLX9284U

Chassis No : JHMGK3850JX216890

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUA JEK HENG

Ins Policy No. :

Date of Accident : 2/3/2022

47732 km

Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: MT101331 OWNER: CHUA JEK HENG ACC DATE: 02/03/2022 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
04631-TAR-300ZZ PANEL SET,R.SIDE	1 ✓	242.90	35	157.88	11.05	168.93
67510-T5A-N10ZZ PANEL COMP,R.RR.DOOR <i>DD</i>	1 ✓	765.20	35	497.38	34.82	532.20
67825-T5A-003 TAPER.RR.DOOR SASH <i>ru</i>	1 ✓	15.40	35	10.01	0.70	10.71
67910-SWA-H11ZZ HINGER.RR.DR.UPPER <i>11</i>	1 X	37.70	35	24.50	1.72	26.22
67920-SWA-H11ZZ HINGER.RR.DR.LOWER <i>11</i>	1 X	37.70	35	24.50	1.72	26.22
72710-T5A-003 REGULATOR ASSYR.RR.DOOR POWER <i>11</i>	1 X	178.50	35	116.02	8.12	124.14
72824-T5A-J01 SUB SEALR.RR.DOOR <i>11</i>	1 X	7.40	35	4.81	0.34	5.15
7326-T5A-003 SEALRR.DOOR LOWER <i>11</i>	1 X	3.80	35	2.47	0.17	2.64
42700-T5S-M72 WHEEL,DISK AL 15X7 <i>page</i>	1 ✓	477.70	35	310.50	21.74	332.24
				Sum Item	1148.07	80.38
						1,228.45
BO-WHEEL ALIGN X4 WHEEL ALIGNMENT X4 <i>202</i>	1 <i>(80)</i>	180.00		180.00	12.60	192.60
				Sum Ext. Service	180.00	12.60
						192.60
BOSUN SUNDRIES <i>202</i>	120	50.00		50.00	3.50	53.50
BOJSE BODY JOINT SEALANT.	180	80.00		80.00	5.60	85.60
BOBC BODY UNDERSIDE COATING (N)	100	100.00		100.00	7.00	107.00
BP00R APPLY BODY UNDERSIDE COATING (N).	250	250.00		250.00	17.50	267.50
BC012R RESET VEHICLE SMART ENTRY SYSTEM <i>202</i>	1	280.00		280.00	19.60	299.60
BKDR22R REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST <i>202</i>	1	350.00		350.00	24.50	374.50

Printed on 3/3/2022 9:21:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer :	TOKIO MARINE INSURANCE SINGAPORE 20 MCCALLUM STREET #09-01	Document No. :	SQT22000625	Page	2
	SINGAPORE 069046	Date	: 2. Mar 2022		
Registration No :	SLX9284U	Customer No.	: WT002		
Chassis No :	JHMGK3850JX216890	Svc Advisor	: SUHELMI		
Model :	JAZZ 1.3LXR CVT 18YM (EURO 6)	Engine No	: L13B11030507		
Owner's Name :	CHUA JEK HENG	Date Time	: 2. Mar 2022 5:48:25 PM		
Ins Policy No. :		Surveyor Name	:		
Date of Accident :	2/3/2022	Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	14% GST Amount	Amount incld GST
SP12R	CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN	1202	2000.00	1800 /	2000.00	140.00	2140.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1202	1300.00	1050 /	1300.00	91.00	1391.00
Sum Labor					4410.00	308.70	4,718.70

Survey By: Tuis / Dan
 Date & Time: 3/3/22 @ 1pm
 Excess: RM 1600
 Status: not in
 Signature: [Signature]

Total Amount 5,738.07 401.68 6,139.75
Total (Inclusive of GST) 6,139.75

parts - 975.77 ✓
 labor - 3378.00 ✓
 Total - \$ 4353.77

Muzical 25/3/22

Printed on 3/3/2022 9:21:33 AM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s).
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.