

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22005994/ECY3M4**Date:** 04/01/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP311813
Claimant Vehicle No :	SBS3354K	Insured Vehicle No :	SMR5186R
Date of Loss:	22/06/2022	Nature of Claim:	TP
		Claim No:	MPC03516/WF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3354K	Engine No:	D9190292
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P920DA161184
Reg. Date:	03/06/2013 (Man. Year: 2013)	Odometer:	537263 km
Colour:	Multi-colour		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,049.48	5,298.73	750.75	12.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,950.00	6,120.00	4,830.00	44.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,999.48	11,418.73	5,580.75	32.83
+ GST 7.00/7.00% (S\$)	1,189.96	799.31	390.65	32.83
Nett Amount (S\$)	18,189.44	12,218.04	5,971.40	32.83

INSPECTION

Date of Assignment:	23/06/2022		
Date Inspected:	24/06/2022	Inspected At:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot Singapore 648170
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jan 2023)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3354K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*OS BUMPER CORNER	Broken	568.94 F	*568.94 FL
2	1		*OS DEFLECTOR	Broken	160.00 F	*160.00 FL
3	1		*OS LIGHT BEZEL	Broken	190.00 F	*190.00 FL
4	1		*NS BEZEL LIGHT	Broken	190.90 F	*190.90 FL
5	1		*NS CORNER BUMPER	Broken	623.86 F	*623.86 FL
6	1		*NS CORNER DEFLECTOR	Broken	211.66 F	*211.66 FL
7	1		*MID BUMPER	Broken	612.28 F	*612.28 FL
8	1		*WINDSCREEN LOWER ASSY	Broken	1,738.08 F	*1,738.08 FL
9	2		*HEADLAMP DIPPED BEAM	Cut	284.80 F	*284.80 FL
10	2		*HEADLAMP MAIN BEAM	Not Necessary	162.00 F	*- FL
11	2		*FRONT LED LAMP INDICATOR	Broken	382.82 F	*382.82 FL
12	1		*FRONT BUMPER LOCK ME	Bent	674.14 F	*674.14 FL
13	1		*TOWER TRANSIT LOGO	Necessary	100.00 F	*100.00 FL
14	1		*SEALANT	Necessary	150.00 F	*150.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,049.48	5,887.48
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	588.75
Total Parts (\$)	6,049.48	5,298.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE ITEM NOS. 1-13	New	1,950.00	975.00
2	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- - FIBER BODY GLASS - LOWER PANEL	New	2,600.00	1,625.00
3	SPRAY PAINTING :- - FIBER BODY GLASS - FRONT LOWER PANEL (3 COLORS) - OS BUMPER CORNER - OS DEFLECTOR - OS LIGHT BEZEL - NS BUMPER CORNER - NS BEZEL LIGHT - OS DEFLECTOR - MID BUMPER	New	6,400.00	3,520.00
			Gross Labour Cost (S\$)	10,950.00
				6,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >