

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005997/TNY3E2**Date:** 28/04/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00011582100
Claimant Vehicle No :	SKS5702U	Insured Vehicle No :	SMP7536L
Date of Loss:	21/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204338C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS5702U		
Make & Model:	PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)	Engine No:	10XT180028117
Reg. Date:	24/04/2015 (Man. Year: 2014)	Chassis No:	VF3LPHNYWES258314
Colour:	Grey	Odometer:	107060 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,815.55	7,282.40	12,533.15	63.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	1,750.00	2,340.00	57.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,905.55	9,032.40	14,873.15	62.22
Approved Total (Overridden) (\$\$)		7,200.00		
(\$\$)	23,905.55	7,200.00	16,705.55	69.88
+ GST 8.00/8.00% (\$\$)	1,912.44	576.00	1,336.44	69.88
Nett Amount (\$\$)	25,817.99	7,776.00	18,041.99	69.88

INSPECTION

Date of Assignment:	23/06/2022	
Date Inspected:	24/06/2022 Inspected At:	H S Automotives PTE LTD (HQ) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2023)
Parts:	144	PEUGEOT 308 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS5702U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,800.92 F	*1,480.00 FL
2	1		*LH FRONT BUMPER RETAINER	Necessary	160.21 F	*100.00 FL
3	1		*FRONT BUMPER CLIP	Necessary	89.00 FS	*40.00 FS
4	1		*LH FRONT BUMPER CHROME MOULDING	Not Necessary	600.17 F	*- FL
5	1		*LH FRONT HEAD LAMP	Cut	2,499.70 F	*2,200.00 FL
6	1		*LH FRONT HEAD LAMP LOWER BRACKET	Not Necessary	197.30 F	*- FL
7	1		*LH FRONT FENDER	Bent	800.91 F	*655.00 FL
8	1		*LH FRONT FENDER INNER SHIELD	Deformed	230.17 F	*138.00 FL
9	1		*LH FRONT FENDER INNER SHIELD CLIP	Necessary	73.00 FS	*20.00 FS
10	1		*LH FRONT DOOR	Repair	2,600.71 F	*- FL
11	1		*LH FRONT SIDE MIRROR	Distorted	1,339.60 F	*950.00 FL
12	1		*LH FRONT SIDE MIRROR COVER (NPA)	Not Necessary	0.00 F	*- FL
13	1		*LH FRONT LOWER ARM	Bent	900.97 F	*492.00 FL
14	1		*LH FRONT WHEEL KNUCKLE	Bent	900.71 F	*665.00 FL
15	1		*LH FRONT WHEEL BEARING	Necessary	700.71 F	*456.00 FL
16	1		*LH FRONT SHOCK ABSORBER	Not Necessary	600.91 F	*- FL
17	1		*LH FRONT LINKAGE ROD	Not Necessary	188.90 F	*- FL
18	1		*POWER STEERING RACK	Not Necessary	4,730.95 F	*- FL
19	1		*STEERING RACK END (NPA)	Not Necessary	0.00 F	*- FL
20	1		*SPORT RIM	Cut	1,400.71 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,815.55	7,996.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	713.60
Total Parts (\$\$)	19,815.55	7,282.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,500.00	700.00
2	SPRAY PAINT	New	1,500.00	700.00
3	TO REMOVE / REFIX UNDERCARRIAGE	New	280.00	150.00
4	TO REMOVE / REFIX POWER STEERING RACK	New	350.00	0.00
5	TO CHECK WIRING	New	100.00	30.00
6	TO REMOVE / REFIX SIDE MIRROR	New	120.00	60.00
7	WHEEL ALIGNMENT	New	120.00	80.00
8	RUST PROOF	New	120.00	30.00
Gross Labour Cost (S\$)			4,090.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >