

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 13.06.2022

MODEL: Hyundai i40

VEHICLE NO.: SHD7146B

INSURANCE: CHINA TAIPING

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 553.00
	Rear Bumper Under Cover	1		\$ 228.00
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	SUB TOTAL			\$ 803.00
	LESS 20%		575	\$ 160.60
	DISCOUNTED TOTAL		460	\$ 642.40
	Rear Bumper Advertisement Sticker	1		\$ 50.00
	Rear Fender Advertisement Sticker RH/LH	2	\$ 100.00	\$ 200.00
	SPARE PARTS TOTAL		250	\$ 892.40
	<u>Labour Charge</u>			
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 300.00
	R/I Reverse Sensors		560	\$ 120.00
	TOTAL LABOUR		1270	\$ 720.00
	ESTIMATE TOTAL		1180	\$ 1,612.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Pamphlet 97415749

- WP' 14/6/22 @ 1050

2 days

temporarily / when work

CLIS Repair after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: