

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	839G
Vehicle Details	
Vehicle No.:	SHB3905P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	2ZRS061475
Chassis No.:	JTDKB3FUX03563344
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	13 Sep 2017
First Registration Date:	13 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$35,265.00
COE Rebate Amount:	\$14,106.00
Total Rebate Amount:	\$17,856.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Jun 2022

OK

Customer: LIM TAN			Date: 6/18/2022 5:09 PM			
Company: 01-42			VIN			
License NO: SHB 3905P			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT TOYOTA, PRIUS PHV ZVW52, 17-17 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°14'	6°35'	8°05'	6°36'
		Right	6°03'	6°35'	8°05'	6°24'
	Camber	Left	-2°18'	-0°55'	0°35'	-2°12'
		Right	-0°30'	-0°55'	0°35'	-0°30'
	Toe	Left	-0°18'	-0°03'	0°08'	-0°15'
		Right	0°12'	-0°03'	0°08'	0°09'
Total		-0°06'	-0°05'	0°16'	-0°06'	
Rear	Camber	Left	-1°24'	-2°00'	-0°30'	-1°18'
		Right	-1°30'	-2°00'	-0°30'	-1°30'
	Toe	Left	0°18'	0°03'	0°14'	0°15'
		Right	0°00'	0°03'	0°14'	0°00'
		Total	0°18'	0°05'	0°27'	0°15'
Thrust Angle		0°09'	----		0°08'	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	13°50'	13°20'	13°20'	13°50'	
	Right	13°41'	13°20'	13°20'	13°41'	
Included Angle	Left	11°32'	----	----	11°38'	
	Right	13°11'	----	----	13°11'	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Max Turn Inside	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	3mm	----	----	3mm	
	Rear	-1mm	----	----	-1mm	
Track Width Diff.		-1mm			-1mm	
Wheel Base Diff.		4mm			4mm	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle					----	

ONE STOP AUTOMOTIVE SOLUTION

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 23-Jun-22

INSURANCE: Budget Direct

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHB 3905 P

DESCRIPTION	QTY	LIST PRICE	AMOUNT
PANEL SUB-ASSY, FRONT DOOR, LH <i>Dist</i>	1	\$1,264.00	\$1,264.00
FRONT DOOR HINGE UPPER <i>src</i>	1	\$91.20	\$91.20
FRONT DOOR HINGE LOWER <i>HW</i>	1	\$91.20	\$91.20
FRONT DOOR CHECK <i>HW</i>	1	\$153.52	\$153.52
FRONT DOOR OUTER MOULDING <i>src</i>	1	\$188.60	\$188.60
FRONT DOOR WHETHER STRIP <i>src</i>	1	\$457.90	\$457.90
FRONT DOOR RUBBER SEAL <i>HW</i>	1	\$257.00	\$257.00
MOTOR ASSY, POWER WINDOW FRT, LH <i>HW</i>	1	\$941.80	\$941.80
REGULATOR, FRONT DOOR WINDOW FRT, LH <i>HW</i>	1	\$228.40	\$228.40
MIRROR ASSY, OUTER REAR VIEW, LH <i>HW</i>	1	\$1,728.70	\$1,728.70
FRONT DOOR ADVERTISEMENT LOGO <i>HW</i>	1	\$100.00	\$100.00
FRONT DOOR COMFORT LOGO <i>HW</i>	1	\$75.00	\$75.00
Rocker Panel Outer Garnish <i>HW</i>	1	\$576.00	\$576.00
Rocker Panel Step Garnish (Front) (LH) <i>HW</i>	1	\$156.50	\$156.50
FRONT BUMPER COVER <i>src</i>	1	\$591.75	\$591.75
LAMP ASSY, FOG, LH <i>HW</i>	1	\$920.00	\$920.00
FRONT BUMPER SIDE RETAINER <i>src</i>	1	\$77.00	\$77.00
UNIT ASSY, HEADLAMP, LH (LED) <i>monthly broken</i>	1	\$3,455.00	\$3,455.00
FENDER SUB-ASSY, FRONT LH <i>cut</i>	1	\$1,111.93	\$1,111.93
FRONT FENDER SHIELD <i>defunct</i>	1	\$255.00	\$255.00
FRONT FENDER SHIELD CLIP <i>HW</i>	1	\$14.90	\$14.90
FRONT FENDER HYBRID EMBLEM, LH <i>HW</i>	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, LH <i>HW</i>	1	\$86.30	\$86.30
EXTENSION, FRONT FENDER, LH <i>HW</i>	1	\$47.20	\$47.20
PROTECTOR, FRONT FENDER UPPER, LH <i>HW</i>	1	\$46.10	\$46.10
GUSSET, FRONT FENDER APRON, LOWER LH <i>HW</i>	1	\$34.90	\$34.90
MEMBER, FRONT APRON TO COWL SIDE, UPPER LH <i>HW</i>	1	\$138.40	\$138.40
FRONT APRON TO COWL SIDE, LOWER FRT LH <i>HW</i>	1	\$82.30	\$82.30
FRONT WHEEL RIM <i>cut</i>	1	\$1,570.55	\$1,570.55
FRONT WHEEL RIM CAP <i>HF</i>	1	\$189.60	\$189.60
FRONT WHEEL HUB AND BEARING <i>Dist</i>	1	\$763.80	\$763.80
FRONT SUSPENSION LOWER ARM (LH) <i>dist</i>	1	\$637.50	\$637.50
FRONT SHOCK ABSORBER (LH) <i>dist</i>	1	\$401.80	\$401.80
ABSORBER TOP MOUNTING <i>HW</i>	1	\$196.20	\$196.20
FRONT DRIVE SHAFT (LH) <i>HW</i>	1	\$1,764.00	\$1,764.00
RACK & PINION ASSY <i>HW</i>	1	\$1,634.90	\$1,634.90
BAR, STABILIZER <i>HW</i>	1	\$360.00	\$360.00
LINK ASSY, FRONT STABILIZER, LH <i>HW</i>	1	\$199.00	\$199.00
KNUCKLE, STEERING, LH <i>dist</i>	1	\$580.80	\$580.80
JOINT ASSY, LOWER BALL, FRONT (LH) <i>HW</i>	1	\$199.98	\$199.98
END SUB-ASSY, TIE ROD, LH <i>HW</i>	1	\$159.30	\$159.30

2637.60

945.30

9,157.75

6,868.31

SUB TOTAL					\$21,914.53
LESS 20% 25%					\$4,382.91
DISCOUNTED TOTAL					\$17,531.62
FRONT FENDER ADVERTISEMENT LOGO (LH) <i>huc</i>	SN	1	\$100.00	\$100.00	
FRONT TYRE (LH) <i>src</i>	SN	1	\$216.00	\$216.00	
SUB TOTAL					\$316.00
Labour Charge					
Panel Beating	1	\$1,800.00	\$1,800.00		
Spray Painting Charge	1	\$1,600.00	\$1,600.00		
Wiring Charge	1	\$100.00	\$100.00		
Tuff Kote	1	\$100.00	\$100.00		
Towing Charge	1	\$80.00	\$80.00		
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00		
Re-set Frt Power Window System	1	\$200.00	\$200.00		
Four Wheel Alignment	1	\$120.00	\$120.00		
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00		
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$150.00	\$150.00		
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00		
TOTAL LABOUR					\$5,180.00
ESTIMATE TOTAL					\$23,027.62
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com					

✓
X
275.00

600/-
600/-
301/-
401/-
Hut
601/-
601/-
1501/-
Hut
1501/-

1690.00

8,833.31

4/5 7,000/-

24/01/2022 e 1000ms

Nut Antenn

2/5m 8dgs.

[Signature]

LKK Ant

Check part prices.

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: