

Huey Yon (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 11 August 2022 9:13 AM
To: Huey Yon (LKKAuto)
Subject: Re: ICS-TP SMR 3565T -SURVEY BY Kenneth (CS/ICS22006005/Kqy3)

Dear Huey Yon,

Audit check done for SMR3565T without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Thursday, 11 August 2022 9:08 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: RE: ICS-TP SMR 3565T -SURVEY BY Kenneth (CS/ICS22006005/Kqy3)

Dear Simon,

Wheel alignment report uploaded.

Best Regards,

Huey Yon | case handler

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Sent: Wednesday, 10 August 2022 5:31 PM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Subject: Re: ICS-TP SMR 3565T -SURVEY BY Kenneth (CS/ICS22006005/Kqy3)

Dear Huey Yon,

Audit check done for SMR3565T, found no wheel alignment report upload.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>

Sent: Wednesday, 10 August 2022 5:21 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: ICS-TP SMR 3565T -SURVEY BY Kenneth (CS/ICS22006005/Kqy3)

Dear Simon,

For your audit.

Best Regards,

Huey Yon | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933