

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/3

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
T MURALI
222 BISHAN STREET 23
#06-159
Singapore 570222

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

23-06-2022
5211001211
200412212G
30001
2022018249/ 1
23-06-2022
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKF1038Z	AD14PY	14-11-2018	WVGZZZ5NZJW963060	Tiguan 1.4actHLBMTFR 110TSID6F	35,554

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS				#1	280.00	299.60
	REPAIR				#1	480.00	513.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	100.00	107.00
9801B001	TO ALIGN LED HEADLIGHT				#1	360.00	385.20
9801B003	B&P WHEEL ALIGNMENT				#1	50.00	53.50
9801B001	R&R RIM & BALANCE				#1	1,459.22	1,561.37
5NA807217J GRU	Cover For Bumper Primed	1	pcs.	1,621.35	10.00%	15.11	16.17
5NA919399 GRU	Sensor Bracket Primed	1	pcs.	16.79	10.00%	15.11	16.17
5NA919400 GRU	Sensor Bracket Primed	1	pcs.	16.79	10.00%	15.11	16.17
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00%	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00%	61.97	66.31
5NA805903A 9B9	Spoiler Satin Black	1	pcs.	379.49	10.00%	341.54	365.45
5NA807049A	Guide Piece	1	pcs.	26.71	10.00%	24.04	25.72
	BUMPER SIDE BRACKET LH	1	pcs.	26.71	10.00%	24.04	25.72
5NA807050A	Guide Piece	1	pcs.	26.71	10.00%	24.04	25.72
	BUMPER SIDE BRACKET RH	1	pcs.	50.06	10.00%	45.05	48.20
5NA853211A 9B9	Trim Satin Black	1	pcs.	50.06	10.00%	45.05	48.20
	LHS FOG LAMP SIDE TRIM	1	pcs.	2,349.36	10.00%	2,114.42	2,262.43
5NC941113E	Led Headlight	1	pcs.	2,349.36	10.00%	2,114.42	2,262.43
	LHS H/LAMP	1	pcs.	21.54	10.00%	19.39	20.75
3C0973737	Flat Contact Housing With	1	pcs.	21.54	10.00%	19.39	20.75
	H/LAMP WIRE HOUSING	1	pcs.	787.24	10.00%	708.52	758.12
5NA821105B	Fender	1	pcs.	787.24	10.00%	708.52	758.12
	RHF FRNDER	1	pcs.	45.43	10.00%	40.89	43.75
5NA821135B	Cross Support	1	pcs.	45.43	10.00%	40.89	43.75
	LHF FENDER BRACKET	1	pcs.	143.24	10.00%	128.92	137.94
5NA805911AG	Wheelhouse Liner	1	pcs.	143.24	10.00%	128.92	137.94
	LHS FENDER LINER	1	pcs.	211.10	10.00%	189.99	203.29
5NA854731E 9B9	Wheel Cover Satin Black	1	pcs.	211.10	10.00%	189.99	203.29
	LHS WHEEL ARCH	8	pcs.	1.84	10.00%	13.25	14.18
3C0853586	Grommet	1	pcs.	1.84	10.00%	13.25	14.18
5NC857507S 9B9	Rear View Mirror Housing	1	pcs.	778.02	10.00%	700.22	749.24
5NA857537 GRU	Mirror Cap Primed	1	pcs.	169.34	10.00%	152.41	163.08
5NA857521A	Mirror Glass	1	pcs.	200.33	10.00%	180.30	192.92
5NA831055N	Door	1	pcs.	2,168.95	10.00%	1,952.06	2,088.70
	LHS FRT DOOR	1	pcs.	241.67	10.00%	217.50	232.73
5NA837701A 5AP	Door Seal Outer Black	1	pcs.	43.65	10.00%	39.29	42.04
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	10.00%	39.29	42.04
	DOOR INSULATION	2	pcs.	5.62	10.00%	10.12	10.83
N 91203801	Bolt With Polygon Socket	2	pcs.	3.12	10.00%	5.62	6.01
WHT005504	Fill. Hd. Screw	1	pcs.	186.01	10.00%	167.41	179.13
5NA837475E VNH	Window Slot Seal With Tri	1	pcs.	186.01	10.00%	167.41	179.13
	LHF DOOR GLASS OUTER MLDG CHROM	1	pcs.	341.02	10.00%	306.92	328.40
5NA854939AFRYP	Cover For Door Satin Black	1	pcs.	341.02	10.00%	306.92	328.40
	LHF DOOR LOWER PROTECTOR	1	pcs.	341.02	10.00%	306.92	328.40

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page 2/3

Company
MSG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details
Mr
T MURALI
222 BISHAN STREET 23
#06-159
Singapore 570222

Document no
Document date 23-06-2022
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 30001
Job order number 2022018249/ 1
Job order date 23-06-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKF1038Z	AD14PY	14-11-2018	WVGZZZ5NZJW963060	Tiguan 1.4actHLBMTFR 110TSID6F	35,554

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
3C0853586	Grommet / <i>npc</i>	8	pcs.	1.84	10.00% #1	13.25	14.18
SNA833055L	Door LHR DOOR / <i>DD</i>	1	pcs.	2,863.18	10.00% #1	2,576.86	2,757.24
SNA839701A 5AP	Door Seal Outer Black / <i>npc</i>	1	pcs.	221.28	10.00% #1	199.15	213.09
D 378500A2	Alu-Lamin. Insulation / <i>nc</i>	1	pcs.	43.65	10.00% #1	39.29	42.04
	DOOR INSULATION						
N 91203801	Bolt With Polygon Socket / <i>nc</i>	2	pcs.	5.62	10.00% #1	10.12	10.83
WHT005504	Fill. Hd. Screw / <i>nc</i>	2	pcs.	3.12	10.00% #1	5.62	6.01
7L6868243	Clip / <i>nc</i>	8	pcs.	1.70	10.00% #1	12.24	13.10
SNA854949AFRYP	Cover For Door Satin Blac / <i>cut</i>	1	pcs.	483.22	10.00% #1	434.90	465.34
	LHR DOOR LOWER PROTECTOR						
SNA601025ABFZZ	Alloy Wheel Black Turned / <i>cut</i>	1	pcs.	2,849.09	10.00% #1	2,564.18	2,743.67
311601361	Rubber Valve / <i>npc</i>	1	pcs.	3.85	10.00% #1	3.47	3.71
	LABOUR	84	pcs.	650.00	#1200	3,900.00	4,173.00
	SPRAY PAINT	85	pcs.	600.00	#1250	3,600.00	3,852.00
	TRANSFER DOOR MECHANISM	2	pcs.	650.00	#1	1,300.00	1,391.00
	MSG MOTORMAXPLUS OD						
	DOA:22/06/2022						
	EXCESS:						
	SURVEY BY:						

Quotation valid till 30-06-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	1,270.00	23,669.74	1,652.12	7%	1,745.78	1,652.12	24,939.74	26,685.52
Total	1,270.00	23,669.74	1,652.12		1,745.78	1,652.12	24,939.74	26,685.52

Steve (LKK)
24/6/22, 2:07p

OD- L1 AL
EXCESS-?
PIP

Customer

Service Advisor

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey damaged parts, using resurvey
- VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No item modification(s) is allowed
- Supply of item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: