

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala

Date: 24 Jun 2022

Preliminary Advice

Vehicle No	: SKF1038Z	Accident Date	: 22/06/2022
Make	: VOLKSWAGEN TIGUAN	Policy No.	: 1001539214
Assignment Date	: 23/06/2022	Excess	: S\$1,500.00
Date of Inspection	: 24/6/2022	Est. Duration of Repair	: 9
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,939.74
Revised Amount	:S\$	20,127.05
Check Items (Estimated)	:S\$	749.13
Total	:S\$	20,876.17
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	129,000.00
COE / PARF Rebate	:S\$	50,982.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,018.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- (X) Part-by-Part repair
- () Lump Sum repair

- (X) Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .