



# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

## GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No: 198003983G

Page 1 / 3

### ESTIMATE

|                 |                                     |               |                                        |
|-----------------|-------------------------------------|---------------|----------------------------------------|
| Date            | : 23/06/2022                        | Reg No        | : YQ5960K                              |
| To              | : UNITED OVERSEAS INSURANCE LIMITED | Model         | : FEA01BR2SDEP CBU MT                  |
| Attn.           | :                                   | Chassis No    | : FEA01BA35337                         |
| Office / Mobile | :                                   | Engine No     | : 4P10E22602                           |
| Email Address   | :                                   | Quotation No. | : 158957                               |
|                 |                                     | Ref. No.      | : GBE/SVC/SALES-HQ/207-2106            |
| From            | : GOLDBELL ENGINEERING PTE LTD      | D.O.A.        | : 21/06/2022                           |
| Attn.           | : CATHERINECHONGKL                  | Policy No.    | : DHOM120064922200                     |
| Office / Mobile | :                                   | Claim Type    | : OD CLAIM - UNITED OVERSEAS INSURANCE |
| Email / Fax No. | : CatherineChongKL@goldbell.com.sg  | Workshop      | : 8 TUAS AVE 18                        |

| S/N | Part No | Description                           | Qty | U/Price  | %   | Net Price | Ext Price          |
|-----|---------|---------------------------------------|-----|----------|-----|-----------|--------------------|
| 1   |         | GLASS,WINDSHIELD <i>cm</i>            | 1   | 1,012.50 | -25 | 759.38    | 759.38             |
| 2   |         | WEATHERSTRIP,WINDSHIELD <i>cm</i>     | 1   | 390.32   | -25 | 292.74    | 292.74             |
| 3   |         | GARNISH,FR PANEL <i>cm</i>            | 1   | 621.07   | -25 | 465.80    | 465.80             |
| 4   |         | GRILLE,RADIATOR <i>cm</i>             | 1   | 410.38   | -25 | 307.78    | 307.78             |
| 5   |         | PANEL, CAB FR CORNER -LH <i>cm</i>    | 1   | 549.75   | -25 | 412.31    | 412.31             |
| 6   |         | PANEL, CAB FR CORNER -RH <i>cm</i>    | 1   | 549.75   | -25 | 412.31    | 412.31             |
| 7   |         | CAP,MIRROR COVER RH <i>met</i>        | 1   | 43.56    | -25 | 32.67     | 32.67              |
| 8   |         | PILLAR,FR RH <i>repair</i>            | 1   | 1,606.60 | -25 | 1,204.95  | 1,204.95 <i>XR</i> |
| 9   |         | MARK,CANTER <i>cm</i>                 | 1   | 115.06   | -25 | 86.30     | 86.30              |
| 10  |         | MARK,THREE-DIA <i>cm</i>              | 1   | 89.66    | -25 | 67.25     | 67.25              |
| 11  |         | PANEL ASSY,FRONT <i>bt</i>            | 1   | 2,832.78 | -25 | 2,124.59  | 2,124.59           |
| 12  |         | STAY,RR VIEW MIRROR -LH <i>bt</i>     | 1   | 497.88   | -25 | 373.41    | 373.41             |
| 13  |         | MIRROR,UNDER VIEW <i>cm</i>           | 1   | 60.35    | -25 | 45.26     | 45.26              |
| 14  |         | COVER,FR BMRP CORNER,LH <i>See</i>    | 1   | 367.25   | -25 | 275.44    | 275.44             |
| 15  |         | COVER,FR BUMPER CORNER,RH <i>See</i>  | 1   | 367.25   | -25 | 275.44    | 275.44             |
| 16  |         | GARNISH,HEADLAMP,LH <i>nn</i>         | 1   | 189.00   | -25 | 141.75    | 141.75             |
| 17  |         | GARNISH,HEADLAMP,RH <i>X nn</i>       | 1   | 189.00   | -25 | 141.75    | 141.75 <i>X</i>    |
| 18  |         | LAMP ASSY,TURN SIGNAL,FR LH <i>br</i> | 1   | 229.26   | -25 | 171.95    | 171.95             |
| 19  |         | LAMP ASSY,TURN SIGNAL,FR RH <i>br</i> | 1   | 229.26   | -25 | 171.95    | 171.95             |
| 20  |         | HEADLAMP ASSY,LH <i>cm</i>            | 1   | 696.91   | -25 | 522.68    | 522.68             |
| 21  |         | HEADLAMP ASSY,RH <i>cm</i>            | 1   | 696.91   | -25 | 522.68    | 522.68             |
| 22  |         | ARM W/SHLD WIPER <i>cm</i>            | 1   | 121.51   | -25 | 91.13     | 91.13              |
| 23  |         | BLADE ASSY,WIPER <i>cm</i>            | 1   | 52.77    | -25 | 39.58     | 39.58              |
| 24  |         | HEATER ASSY <i>? Xnn</i>              | 1   | 2,942.91 | -25 | 2,207.18  | 2,207.18 <i>X</i>  |
| 25  |         | DUCT,AIR CLEANER INTAKE <i>? Xnn</i>  | 1   | 790.78   | -25 | 593.09    | 593.09 <i>X</i>    |

PARTS TOTAL : 7592.40 11,739.37


#### SPECIAL NETT ITEMS

|   |                           |   |                        |
|---|---------------------------|---|------------------------|
| 1 | IU BRACKET <i>nn</i>      | 1 | 15.00                  |
| 2 | COMPANY STICKER <i>nn</i> | 1 | 150 200.00 <i>1165</i> |

PARTS TOTAL: 215.00

FUSO AIRMAN.

bizSAFE  
ST & R





## ESTIMATE

|                   |                                   |                 |                                      |
|-------------------|-----------------------------------|-----------------|--------------------------------------|
| Date :            | 23/06/2022                        | Reg No :        | YQ5960K                              |
| To :              | UNITED OVERSEAS INSURANCE LIMITED | Model :         | FEA01BR2SDEP CBU MT                  |
| Attn. :           |                                   | Chassis No :    | FEA01BA35337                         |
| Office / Mobile : |                                   | Engine No :     | 4P10E22602                           |
| Email Address :   |                                   | Quotation No. : | 158957                               |
|                   |                                   | Ref. No. :      | GBE/SVC/SALES-HQ/207-2106            |
| From :            | GOLDBELL ENGINEERING PTE LTD      | D.O.A. :        | 21/06/2022                           |
| Attn. :           | CATHERINECHONGKL                  | Policy No. :    | DHOM120064922200                     |
| Office / Mobile : |                                   | Claim Type :    | OD CLAIM - UNITED OVERSEAS INSURANCE |
| Email / Fax No. : | CatherineChongKL@goldbell.com.sg  | Workshop :      | 8 TUAS AVE 18                        |

### LABOUR CHARGES

|   |                                                                                     |                      |         |
|---|-------------------------------------------------------------------------------------|----------------------|---------|
| 1 | TO REMOVE AND REFIX FRONT WINDSCREEN                                                | 120                  | 150.00  |
| 2 | TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC | 2700                 | 4000.00 |
| 3 | TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK                | 150                  | 180.00  |
| 4 | REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION                               | X <sup>11</sup> 600? | 700.00  |
| 5 | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC                                        | 1400                 | 2000.00 |
| 6 | TO REMOVE AND INSTALL MOBILEYE                                                      | X <sup>11</sup> 600  | 350.00  |
| 7 | TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD                                   |                      | 700.00  |

4720

|                             |                  |
|-----------------------------|------------------|
| LABOUR TOTAL :              | 8,080.00         |
| SUB-TOTAL :                 | 20,034.37        |
| GST @ 7% for \$ 20,034.37   | 1,402.41         |
| <b>GRAND TOTAL (\$\$) :</b> | <b>21,436.78</b> |

LKK Auto Consultants shall notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 7592.40  
 SN - 165.00  
 L - 4720.00  
 Supp - 280.27  
 T - 12,757.67